



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lim Choo Siang Blk 256 Serangoon Central Drive #07-36 Singapore 550256 Contact No Mobile: 93822021	Cust No/Name /Lim Choo Siang Reg No/Reg Date SLQ1868A / 29/06/201 Date In/Mileage / 0 Chassis No KNAFJ411MH5721371 Engine No G4FGGH637550 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	23/05/2022/ 12:57	BLC	442 / CocoLu	51447		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, REAR FENDER RH, REPAIR REAR LAMP HOUSING RH							2560 3200.00
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN							300.00
M SUNDRY SEALANT FOR WINDSCREEN							80.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, REAR FENDER RH, REAR LAMP HOUSING RH							1190 1650.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							280.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION							40.00
E PNT88000 REMOVE & INSTALL REAR COMPARTMENT TRIMS AND REAR FENDER TRIMS							260 300.00
M SUNDRY Sundry							20.00
M COVER-RR BUMPER				1.00	688.00	00.00	688.00
M GUARD-BUMPER REAR, RH				1.00	23.00	00.00	23.00
M BRACKET-RR BUMPER SIDE MTG, RH				1.00	39.00	00.00	39.00
M PANEL ASSY-QUARTER OUTER, RH				1.00	1673.00	00.00	1673.00
M PANEL ASSY-RR COMB LAMP HSG, RH				1.00	229.00	00.00	229.00
M LAMP ASSY-REAR COMBINATION, RH				1.00	368.00	00.00	368.00
M MOULDING-REAR WINDOW GLASS				1.00	32.00	00.00	32.00

Steve (LKK)
21/6/22, 1.00p

m n
PIP
H BL y

Steve (LKK)
21/6/22, 1.00pm n
P/P
H BL y

Confirm & accepted by LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed

Authorized signatory and company stamp resurveyed and

8 d/s

7% GST on Nett 8,952.00 8,952.00
Total Payable 626.64 9,578.64

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are, excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.