

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005808/AYA3Q2
Date: 06/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800084149
Claimant Vehicle No :	SLJ1301E	Insured Vehicle No :	SKT3113C
Date of Loss:	03/04/2022	Nature of Claim:	TP
		Claim No:	2776939776SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ1301E		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Engine No:	1ZR589034
Reg. Date:	29/11/2016 (Man. Year: 2016)	Chassis No:	MR053REH104555838
Colour:	Grey	Odometer:	167177 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,099.90	1,699.80	6,400.10	79.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	1,330.00	1,880.00	58.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,309.90	3,029.80	8,280.10	73.21
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	11,309.90	2,400.00	8,909.90	78.78
+ Loss of Use (5.0 x S\$70.00/day) (S\$)		350.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,757.45		

INSPECTION

Date of Assignment:	04/04/2022		
Date Inspected:	04/04/2022	Inspected At:	YSK Auto Workshop (HQ) 1 Kaki Bukit Avenue 6 @ AutoBay, #01-71 Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	482.20 F	*482.20 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*REAR BUMPER SIDE HOLDER LH	Necessary	35.20 F	*35.20 FL
4	1		*REAR LH FENDER	Repair	965.30 F	*- FL
5	1		*REAR LH FENDER INNER SHIELD	Not Necessary	79.50 F	*- FL
6	1		*REAR LH FENDER INNER SHIELD CLIPS	Not Necessary	20.00 FS	*- FS
7	1		*REAR LH FENDER INNER SHIELD GUARD	Cut	29.40 F	*29.40 FL
8	1		*REAR WINDSCREEN MOULDING	Not Necessary	180.20 F	*- FL
9	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
10	1		*REAR LH WHEEL RIM	Cut	800.00 FS	*450.00 FS
11	1		*REAR LH TYRE	Not Necessary	280.00 FS	*- FS
12	1		*REAR AXLE	Not Necessary	2,855.00 F	*- FL
13	1		*REAR LH SHOCK ABSORBER	Not Necessary	296.40 F	*- FL
14	1		*REAR LH WHEEL HUB C/W BEARING	Not Necessary	357.50 F	*- FL
15	1		*REAR LH DOOR	Dented	1,079.60 F	*1,079.60 FL
16	1		*REAR LH DOOR LOCK	Not Necessary	371.20 F	*- FL
17	1		*REAR LH DOOR WEATHERSTRIPE	Not Necessary	178.40 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,099.90	2,106.40
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	406.60
Total Parts (\$)	8,099.90	1,699.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	500.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	40.00
5	TO REMOVE UPHOLSTERY	New	150.00	0.00
6	TO REMOVE REAR WINDSCREEN	New	180.00	0.00
7	TO REMOVE REAR UNDERCARRIAGE	New	380.00	0.00
8	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
9	TO TRANSFER DOOR FITTINGS	New	150.00	80.00
			Gross Labour Cost (S\$)	3,210.00
				1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >