

SLJ 1301E. 2016 Nov
Toyota Altis 1598cc

TP Alig.
Ashes.

MROS3REH104555838

Rear Bumper	Deformed	482.20	✓
Rear Bumper Clips.	nr	30(SN)	✓
Rear Bumper Side Holder LH.	nr	35.20.	✓
Rear LH Fenders	Repis	965.30	+
Rear LH Fender Lower Shield	2 NP	79.50	+
Rear LH Fender Lower Shield Clips.	nr	20(SN)	+
Rear LH Fender Lower Shield Guard.	Cut	29.40	✓
Rear Windscreen Moulding	NP	180.20	+
Rear Windscreen Sealant.	nr	60(SN)	+
Rear LH Wheel Rim.	Cut	800(SN) 450(SN)	
Rear LH Tyre.	NP	280(SN)	+
Rear Axle	nr	2855	+
Rear LH Shock Absorber	NP	296.40	+
Rear LH Wheel Hub c/o Bearing.	NR nr	357.50	+

SLJ 1301E.

Rear LH Door Dented 1079.60 ✓

Rear LH Door lock } NP 371.20 x

Rear LH Door Weatherstripe } We 178.40. x

1626.40

S.N. 480

1219.80

Panel Beating

~~1000~~ 500

Spray Painting

~~1000~~ 600

Wiring.

~~50~~ 30

To spray full coat

~~150~~ 40

To remove upholstery.

150 x

To remove rear windscreen.

180 x

To remove rear undercarriage.

1330

380 x

To perform wheel alignment.

~~150~~ 80

To transfer door fittings

~~150~~ 80

Total: 3029.80

L/S: 24K

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

24K