

ASS. REC. BY:

REF:

A16/ 220058161ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 1.131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SNI- 2700C

Yr Regn:

OF

18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A1

Spot Ca

Make:

Porsche Boxster GTS 2497

Colour

M.D. Blue

A/C:

Insured / Std / Nil / NA

Sp. Reading

1466

T/Radio:

Insured / Std / Nil / NA

Eng/No:

C/No:

WPO 777 987 JS 221249

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

235/35ZR20

R:

265/35ZR20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

7

mm

L/Bal.

6

mm

L/Bal.

7

mm

D.O.A.

15/6/22

D.O.A.

20/6/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/8 @ 3792.79 Contd

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Date: 17/06/2022

Vehicle No: SNF2700C

Model: PORSCHE 718 BOXSTER GTS

Chassis: WPOZZZ98ZJS221249-2018

Reg.Year: 2021

Third Party Insurer: AIG

Third Party Veh No: SMU5621K

Date of Accident: 15/06/2022

Estimator: TING AN

Surveyor:

*Not Withheld
Minor After Rain*

*2 days
@ 3792.79*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>R</i> \$2,300.00
2	REAR BUMPER SIDE RETAINER RH	1		<i>R</i> \$270.00
3	REAR FENDER RH	1		<i>R</i> \$8,640.00
4	REAR RIM RH <i>3053-10</i>	1		<i>R</i> \$4,050.00
5	REAR ABSORBER RH	1		<i>R</i> \$1,360.00
6	REAR LOWER ARM RH	1		<i>R</i> \$1,360.00
7	REAR TIE ROD RH	1		<i>R</i> \$640.00
SUB TOTAL				\$18,620.00
LESS 10%				-\$1,862.00
PARTS TOTAL				\$16,758.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>nn</i> \$80.00
	<i>Rear A14 type</i>		<i>nn</i>	<i>450.00</i>
S/N TOTAL				\$80.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.

\$600.00 *200*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR FENDER RH & ETC.

\$600.00 *440*

LABOUR CHARGES TO REMOVE & REPLACE REAR ABSORBER RH, REAR LOWER ARM RH, REAR TIE ROD RH & ETC.

nn \$300.00 *X*

LABOUR CHARGES TO REMOVE & REPLACE REAR RIM RH.

\$150.00 *300*

TO WHEEL ALIGNMENT & BALANCING.

\$100.00 *600*

TO CHECK WIRING & ELECTRICAL SYSTEM

nn \$120.00 *X*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$1,870.00

TOTAL \$18,708.00

TING AN

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500 Tel: (+65) 6484 9919 Fax: (+65) 6484 9919
Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047 Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

Signature:

Date:

