



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF22005820/Kvy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB)			Date:	20/07/2022
1 HEMMANT ROAD SINGAPORE 438675				
ATTN: HAFIZUL FARHAN			Code:	SPF
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YP 3816M	Veh. Inspected	SLU 1198D	
Policy No.		Coverage (\$)	0.00	
Claim No.	ACS/105/009/2022/034	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	20/06/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA FREED (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GB71040652	Colour	METALLIC PEARL WHITE	
Odometer	100026 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/50 R16	BRIDGESTONE	5 mm	
L/H Front Tyre	205/50 R16	BRIDGESTONE	5 mm	
R/H Rear Tyre	205/50 R16	BRIDGESTONE	7 mm	
L/H Rear Tyre	205/50 R16	BRIDGESTONE	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	19/06/2022	Inspection Date	20/06/2022	
Survey held at	LH EXPRESS MOTOR TRADING BLK 5038 ANG MO KIO AVE 3 #01-405 ANG MO KIO IND. PARK 2 SINGAPORE 569541			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	