

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3071/06/22

Your Ref: _____

Date: 20th JUNE 2022

Madam Loo Chwee Ngoh
Blk 241, #08-1096
Yishun Ring Rd, S(760241)

Estimate cost of repair to TOYOTA COROLLA ALTIS 1.6 (A) Saloon - SDW 5905 M

1 pc rear bumper		\$ 582.20
10 pcs rear bumper clips	@ \$ 4.80	48.00
1 pc rear bumper reinforcement		362.20
1 set rear bumper reverse sensor		388.20
2 pcs rear bumper o/s & n/s side retainer @ \$ 114.40		<u>228.80</u>

\$ 1,609.40

Less 25% \$ 402.35

\$ 1,207.05

To wiring check up for reverse sensor 30.00

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts. 300.00

To putty & respray painting on all affected parts. 380.00

\$ 1,917.05
=====

Dollars : One Thousand Nine Hundred Seventeen And Cents Five Only.

HUP MOTOR TRADING & SERVICE

.....


INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SLK850m

Date of Accident

16/06/2022



Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance **AIG Asia Pacific Insurance Pte....**

Period of Insurance **13/01/2022 - 12/01/2023**

Requested By **sandy (Hup Motor Trading & S...**

Requested Date **16/06/2022 22:24**

Payment details

Request Amount: **S\$1.87**

GST Amount: **S\$0.13**

Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**