

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3071/06/22

Your Ref: \_\_\_\_\_

Date: 20th JUNE 2022

Madam Loo Chwee Ngoh  
Blk 241, #08-1096  
Yishun Ring Rd, S(760241)

### Estimate cost of repair to TOYOTA COROLLA ALTIS 1.6 (A) Saloon - SDW 5905 M

1 pc rear bumper		\$ 582.20 ✓
18cf <del>10 pcs</del> rear bumper clips	<del>4.80</del>	48.00 ✓
1 pc rear bumper reinforcement		362.20 X
1 set rear bumper reverse sensor		388.20 X
2 pcs rear bumper o/s & n/s side retainer @ \$ 114.40		<del>228.80</del> X
		<hr/>
		\$ 1,609.40
	Less 25%	\$ 402.35
		<hr/>
		\$ 1,207.05

To wiring check up for reverse sensor 30.00 ✓

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts. 300.00 200

To putty & respray painting on all affected parts. 380.00 300

---

\$ 1,917.05  
=====

Dollars : One Thousand Nine Hundred Seventeen And Cents Five Only.

HUP MOTOR TRADING & SERVICE



*not authorized*  
*llr*  
*20/06/22*  
*1/5 \$800*  
*2 days*  
*Edapha Alvin*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*P-630-2*  
*252*  
*472-65*  
*530*  
*1002-65*  
*205*  
*802-12*