

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 27 Sep 2022

Preliminary Advice

Vehicle No	: GBJ2341B	Accident Date	: 11/06/2022
Make	: ISUZU TFR86JSR	Policy No.	: DMCVSNW00019062201
Assignment Date	: 17/06/2022	Excess	: S\$500.00
Date of Inspection	: 20/06/2022	Est. Duration of Repair	: 7
Inspection At	: JIN AUTO SERVICES PTE LTD (DEFU) BLK 14 DEFU LANE 10, #01-410/412 SINGAPORE 539195		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,147.21 (Inclusive of supplementary \$1560.0
Revised Amount	:S\$	8,427.21 (Inclusive of supplementary)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,427.21
Lump Sum Repair	:S\$	7,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	58,000.00
COE / PARF Rebate	:S\$	16,412.00
Salvage Value	:S\$	
Margin for Repair	:S\$	41,588.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :KINDLY APPROVE ON SUPPLEMENTARY.