

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

KNAPH 81 BMJS 417817.

TPA x A

VERON

SMZ1808P Kia Sorento

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy (upper) <i>Delud</i>	\$ 1,267.00 696.
2	1	Rear bumper assy (lower)	\$ 1,189.00 565.
3	2	Rear bumper bracket <i>new</i>	\$ 188.00 +
4	1	Rear bumper reinforcement <i>new</i>	\$ 393.00 +
5	1	Rear bumper tow cover <i>Delud</i>	\$ 95.00 38
6	1 set	Rear bumper reflector <i>RH cml'd.</i>	\$ 348.00 174
7	1 set	Rear bumper reflector garnish <i>RH cml'd</i>	\$ 225.00 112.50
8	1	Rear bumper top moulding <i>new</i>	\$ 297.00 ✓
9	1	Rear tailgate assy <i>Repic</i>	\$ 2,892.00 +
10	1	Rear tailgate lock mechanism <i>new</i>	\$ 301.00 x
11	1	Rear tailgate inner trim board <i>new</i>	\$ 303.00 +
12	1	Rear tailgate inner handle <i>green</i>	\$ 98.00 +
13	1	Rear tailgate weatherstrip	\$ 288.00 +
14	2	Rear tailgate hinges <i>green</i>	\$ 186.00 +
15	2	Rear tailgate dampers	\$ 1,365.00 +
16	1	Rear tailgate inner lamp <i>green</i>	\$ 95.00 +
17	1	Rear tailgate push button switch <i>green</i>	\$ 165.00 +
18	1	Rear tailgate centre logo <i>new</i>	\$ 128.00 ✓
19	1	Rear end lower panel <i>Rested</i>	\$ 1,098.00 681
20	1	Rear end lower panel top garnish <i>cml'd</i>	\$ 265.00 ✓
21	4	Rear exhaust muffler assy rubber mounting <i>new</i>	\$ 88.00 +
22	1	Rear exhaust muffler assy <i>new</i>	\$ 1,610.00 x
23	1	Rear exhaust tail pipe cover <i>new</i>	\$ 250.00 x
24	1	Rear windscreen glass moulding	\$ 388.00 +
25	1	Rear left fender protector <i>green</i>	\$ 197.00 +
26	1	Rear right fender protector	\$ 197.00 +
27	1	Tailgate Switch = \$290 <i>not tax</i>	\$ 13,916.00
		less 10%	\$ 1,391.60
		<i>paid ✓</i>	\$ 12,524.40

3246.50

Less 10%: 2921.85

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMZ1808P Kia Sorento

			Estimated Parts Price	
No	Qty	Parts Description		
<u>Special Nett Items</u>				
1	16	Rear bumper clips <i>new</i>	\$	60.00 30
2	8	Rear tailgate inner trim board clips <i>new</i>	\$	50.00 <i>+</i>
3	1	Rear end lower panel sealant <i>new</i>	\$	140.00 60
4	6	Rear end lower panel top garnish clips <i>new</i>	\$	50.00 10.
5	4	Rear left fender protector clips <i>3 new</i>	\$	30.00 <i>4</i>
6	4	Rear right fender protector clips	\$	30.00 <i>4</i>
7	2	Rear bumper reverse sensor <i>Damaged</i>	\$	600.00 420
8	1	Rear bumper lower diffuser <i>Behind</i>	\$	1,200.00 550
9	1	Rear bumper lower diffuser sealant <i>new</i>	\$	100.00 30
10	10	Rear bumper lower diffuser clips <i>new</i>	\$	50.00 50
11	1	Rear view camera <i>new</i>	\$	450.00 <i>+</i>
12	1	Rear no plate with garnish <i>new</i>	\$	100.00 <i>+</i>
13	1 set	Rear LED lamp <i>Damaged</i>	\$	450.00 200
14	1	Rear windscreen glass sealant <i>new</i>	\$	100.00 <i>+</i>
			\$	<u>3,410.00</u>
Total parts			\$	15,934.40

1590

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMZ1808P Kia Sorento

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,000.00 600
2	To putty and spray painting rear portion.	\$ 1,000.00 600
3	To remove and install rear view camera.	\$ 80.00 x
4	To remove and install rear tailgate lock mechanism.	\$ 80.00 x
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 180.00 40
6	To wrap rear bumper top moulding with black colour.	\$ 180.00 150
7	To wrap rear bumper complete assy with grey colour.	\$ 600.00 300
8	To wrap rear tailgate assy with grey colour.	\$ 800.00 350
9	To apply anti rust proofing to rear affected area.	\$ 140.00 50
10	To remove and install rear bumper reverse sensor.	\$ 80.00 50
11	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 x
Total labour :		\$ 4,280.00

Total parts : \$ 15,934.40

Total labour : \$ 4,280.00

Total repair cost : \$ 20,214.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lg
 2/5 21/06/22
 05 Days.

total: 6651.85

2/5: 5.3K

5.3K