

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL : 96273323 FAX 68442641

CO.REG NO. : 53049097-L

TP AIG.

Xiao Tony

TANG SIA CHUA

BLK 23 BEDOK SOUTH AVENUE 1 #07-771

SINGAPORE 460023

DATE : 18/09/2022

MODEL : MITSUBISHI ATTRAGE 1.2 CVT

CHASSIS NO. : MMBSTA13AKH001147

ESTIMATE COST OF REPAIR BILL TO MITSUBISHI CAR NO. : SMJ7935A

1 PC REAR BOOTLID <i>Dented.</i>	\$ 828.00	N	✓
1 PC REAR BOOTLID LOCK <i>Damaged</i>	\$ 206.00	N	✓
1 PC REAR BOOTLID RUBBER <i>Cut</i>	\$ 148.00	N	✓
1 PC REAR ATTRAGE EMBLEM	\$ 38.00	N	✓
1 PC REAR MIT EMBLEM	\$ 41.00	N	✓
1 PC REAR MIVEC EMBLEM	\$ 40.00	N	✓
1 PC C&C EMBLEM	\$ 35.00	N	✓
1 PC REAR BOOTLID CHROME MOULDING <i>new</i>	\$ 318.00	N	×
2 PC REAR BOOTLID HINGE	\$ 384.00	N	×
1 PC REAR BOOTLID SPOILER LID <i>new</i>	\$ 380.00	S/N	×
1 PC REAR REVERSE CAMERA	\$ 380.00	S/N	×
2 PC REAR TAILLAMP <i>Cut</i>	\$ 592.00	N	✓
8 PC REAR TAILLAMP CLIP <i>new</i>	\$ 40.00	N	20. ✓
1 PC REAR L/H TAILLAMP PANEL <i>Buckled.</i>	\$ 170	N	✓
1 PC REAR L/H FENDER <i>Buckled.</i>	\$ 725.00	N	✓
1 PC REAR R/H FENDER <i>Repair</i>	\$ 725.00	N	×
2 PC REAR (R/H & L/H) FENDER INNER TRIMBOARD <i>Lit torn</i>	\$ 360.00	N	180. ✓
1 PC REAR END PANEL <i>Dented.</i>	\$ 465.00	N	✓
1 PC REAR END PANEL LOCK <i>new</i>	\$ 38.00	N	×
1 PC REAR END PANEL GARNISH <i>Dehanded</i>	\$ 68.00	N	✓
4 PC REAR END PANEL GARNISH CLIP <i>new</i>	\$ 20.00	N	✓
1 PC REAR END PANEL AIR GRILLE GARNISH <i>Dehanded</i>	\$ 45.00	N	✓
1 PC REAR END PANEL AIR GRILLE COVER GARNISH	\$ 42.00	N	✓
2 PC REAR END PANEL AIR GRILLE COVER GARNISH CLIP <i>new</i>	\$ 10.00	N	✓
1 PC REAR BUMPER <i>Distorted</i>	\$ 728.00	N	✓
2 PC REAR BUMPER SIDE RETAINER <i>new</i>	\$ 72.00	N	✓
8 PC REAR BUMPER CLIP <i>new</i>	\$ 40.00	N	✓
2 PC REAR BUMPER REFLECTOR <i>crushed.</i>	\$ 76.00	N	✓
1 PC REAR BUMPER LOWER SKIRT <i>Distorted</i>	\$ 850.00	S/N	750(SN) ✓
2 PC REAR BUMPER SIDE INNER SHIELD GARNISH <i>torn</i>	\$ 56.00	N	✓

4 PC REAR BUMPER SIDE GARNISH CLIP *Nec*
 1 SET REVERSE SENSOR *Damaged*
 1 PC SPARE WHEEL BOARD *torn*

\$ 20.00 N ✓
 \$ 200.00 S/N ✓
 \$ 228.00 N ✓

PAGE 1 OF 2

1 PC KEYLESS SENSOR *and*
 1 PC KEYLESS SENSOR BRACKET *Nec Nec*
 1 PC ANTENNA SENSOR *Damaged*

\$ 110.00 N ✓
 \$ 12.00 N X
 \$ 116.00 N ✓

2 PC REAR END PANEL INNER SIDE GARNISH } *Nec Nec*
 6 PC REAR END PANEL INNER SIDE GARNISH CLIP }

\$ 316.00 N X
 \$ 30.00 N X

1 PC SPARE TYRE PANEL *Repair*
 1 PC REAR WINDSCREEN MOULDING } *Nec*
 1 PC REAR WINDSCREEN INNER SEAL }
 1 PC REAR WINDSCREEN SEALANT }

\$ 916.00 N +
 \$ 85.00 N ✓
 \$ 26.00 S/N ✓
 \$ 45.00 S/N ✓

5204
 4683-60
 S/N: 1021

LABOUR CHARGE

TO CHECK WIRING
 TO SPRAY PAINTING(PEARL RED)
 TO REMOVE & REFIX REAR INTERIOR UPHOLSTERY
 TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED
 PANEL FOR RUST PROTECTION
 TO MEASURE & DRILL REAR BUMPER , POSITION & INSTALL REAR
 REVERSE SENSOR , REAR CAMERA , CONTROL UNIT , CHECK & TEST
 FOR FUNCTIONING
 TO PANEL BEATING , WELDING REMOVE ALL DAMAGE
 PARTS & REPLACING OF THE NEW PARTS ETC.

\$ 50.00 *30*
 \$ 1,800.00 *1400*
 \$ 150.00 *60*
 \$ 80.00 ✓

\$ 80.00 ✓
 \$ 1,600.00 *1400*

To remove rear windscreen.

3170
180
120

TOTAL \$ 13,684.00

total: 8874.60

L/c: 7.1K

10 Days.

7.1K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: