

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jacqueline Tan

Date: 20 Jun 2022

## **Preliminary Advice**

Vehicle No	: GBG585T	Accident Date	: 14/06/2022
Make	: NISSAN NV200	Policy No.	: DMCVSNA00094542100
Assignment Date	: 20/06/2022	Excess	: S\$2,000.00
Date of Inspection	: 20/06/2022	Est. Duration of Repair	: 6
Inspection At	: S & H MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #07-02, SIN MING AUTOCITY SINGAPORE 575722		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,829.15
Revised Amount	:S\$	3,802.15
Check Items (Estimated)	:S\$	3,375.00
Total	:S\$	7,177.15

Lump Sum Repair	:S\$	
-----------------	------	--

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	43,000.00
COE / PARF Rebate	:S\$	15,160.00

Salvage Value	:S\$
Margin for Repair	:S\$ 27,840.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
  
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
  
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.