

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 14/06/2022

Estimated repair cost for vehicle no: SNA6507U TOYOTA VELLFIRE ELEGANCE

MOONROOF (AUTO)

CHASSIS: JTNGF3DH408022465 (2019)

15/06/2022

7P ALG

Xiao Tony

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>Dehnd</i>	\$889.10	\$889.10 ✓
2	1	REAR BUMPER SIDE RETAINER RH <i>Dehnd</i>	\$230.79	\$230.79 ✓ 110
3	1	REAR BUMPER REFLECTOR <i>Dehnd</i>	\$121.30	\$121.30 ✓
4	1	RH REAR TAILLAMP <i>Dehnd</i>	\$789.10	\$789.10 ✓ 635
5	1	RH REAR TAILLAMP APRON PANEL <i>Dehnd</i>	\$389.10	\$389.10 ✓
6	1	RH REAR TAILLAMP APRON BRACKET <i>Dehnd</i>	\$231.80	\$231.80 ✓ 58
7	1	RH REAR FENDER <i>Rejs</i>	\$1,712.90	\$1,712.90 ✓
8	1	RH REAR FENDER INNER COWLING <i>torn</i>	\$378.10	\$378.10 ✓ 295
9	1	RH REAR FENDER STOPPER <i>Not in</i>	\$43.20	\$43.20 ✓
10	1	RH REAR FENDER MUDFLAP <i>Not in</i> Nec	\$278.90	\$278.90 ✓ 210
1	1	RH REAR WHEEL BEARING <i>Not in</i> Nec	\$483.50	\$483.50 ✓

2750.70
2063.02

TOTAL :	\$5,247.79
LESS 25 %	\$1,311.95
SUB-TOTAL :	\$3,935.84

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER REVERSE SENSOR RH <i>Not in</i>	\$380.00	\$380.00 ✓
2	1	REAR BUMPER CLIPS <i>Not in</i>	\$80.00	\$80.00 ✓ 30
3	1	RH REAR SPORT RIM <i>Not in</i>	\$1,300.00	\$1,300.00 ✓
4	1	RH REAR TYRE <i>Not in</i>	\$380.00	\$380.00 ✓
5	1	RH REAR TAILLAMP APRON PANERL CLIPS <i>Not in</i>	\$50.00	\$50.00 ✓ 20
6	1	RH REAR FENDER GLASS SEALANT <i>Not in</i>	\$120.00	\$120.00 ✓
7	1	RH REAR FENDER SEALANT <i>Not in</i>	\$150.00	\$150.00 ✓
8	1	RH REAR FENDER INNER COWLING CLIPS <i>Not in</i>	\$60.00	\$60.00 ✓ 20

70

TOTAL:	\$2,520.00
TOTAL PARTS	\$6,455.84

SNA6507U TOYOTA VELLFIRE

Labour charges

1	LABOUR FOR PANEL BEATING	\$1,600.00	\$600
2	LABOUR FOR SPRAYPAINTING	\$1,400.00	700
3	WIRING CHECK	\$80.00	30
4	LABOUR FOR REMOVE & REFIX RH REAR FENDER GLASS	\$150.00	x
5	LABOUR FOR REMOVE & REFIX REAR UPHOSLTERY /ROOF LINING	\$300.00	x 60
6	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS	\$300.00	60

Subtotal :- \$3,830.00

Total:- \$10,285.84

Admin Lj
L/s 15/06/22.

04 Days.

Supplementary: 1304.57

Total: 4787.59

L/s: 3.81c

38K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 14/06/2022

Estimated repair cost for vehicle no: SNA6507U TOYOTA VELLFIRE ELEGANCE

CHASSIS: JTNGF3DH408022465 (2019)

15/06/2022

S/N	Qty	Items	U/price	Amount
1	1	RH REAR BUILD SPOT SENSOR <i>included</i>	\$1,817.90	\$1,817.90 ✓ 1320
2	1	RH REAR BUILD SPOT SENSOR BRACKET <i>new</i>	\$121.40	\$121.40 ✗
3	1	RH REAR BUMPER LOWER GARNISH COVER <i>new</i>	\$86.10	\$86.10 ✓

To calibrate blind spot sensor. *300*
250.

TOTAL :	\$2,025.40
LESS 25 %	\$506.35
SUB-TOTAL :	\$1,519.05

Adnan Lij
15/06/22.

1406.10
Supplementary: 1054.57

Supplementary: 1304.57.