

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLZ 5981 G. 2018 May.

TPAXA

Toyota Noah, Hybrid 1797cc. Veron.

ZWR 800302839

Rear Bumper.

Deformed

1025.10. ✓

Rear Bumper Clips.

Nec

~~50(SN)~~ 30(SN).

Rear Bumper Side Holder RH. cracked

78.90 ✓

Rear Bumper Reflector RH. ~~MR~~ ~~MR~~

92.90 +

Taillap RH. cracked.

781.40 ✓

Taillap lower Apron RH. Deformed

376.90. ✓

Taillap Panel RH. Reps

697.40 +

2262.30

SN: 30.

1696.72

Panel Beating

~~500~~ 300

Spray Painting.

880

~~600~~ 500

Wiring.

~~50~~ 30

To reuse reuse sensor.

~~100~~ 50.

4352.60

total: 2606.72

H/s: 2K.

04 Days