

SMU2562S. 2020 August.
 TP MS16. Hyundai Accent. 1368CC
 Celline. KMHC441BTK4481927

Rear Number Plate.	} NH Mer	30(SN) X
Rear Number Plate Holder		30(SN) X.
Rear Bumper Deformed		545.30 ✓
Rear Bumper Clips. Mer		30(SN) ✓
Rear Bumper Side Holder x 02	DR	44.8 x 2 = 89.60 ✓
Rear Bumper Reflector x 02	RH and	154.6 x 2 = 309.20 ✓ 154.60
Rear Bumper Reinforcement Curved		376.50 ✓
Rear Bumper Reinforcement Bracket Upper x 02	RH and	25 x 2 = 50 ✓ 25
Rear Bumper Reinforcement Bracket Lower x 03.	1 piece and	25 x 3 = 75 ✓ 25
Tailcap x 02	RH and	388.4 x 2 = 776.80 ✓ 388.40
Tailcap Panel RH.	Dented	278.40 ✓
Reverse Sensor x 04	2 pieces and	185 x 4 = 740 ✓ 370
Reverse Sensor Holder x 04. Mer		25 x 4 = 100 ✓
Rear End Panel.	Dented	499.30 ✓

SMU2562S.

Rear End Panel Top Garnish.	Delivered	125.50	—
Rear End Panel Top Garnish Clips.	m	20(SN)	✓
Rear End Panel Sealant	m	60(SN)	✓
Bootlid	Dented	1225.90	—
Bootlid Lock	2nd	175.40	✓
Bootlid Weatherstripe. Lt		192.60	✓
Hyundai Logo.	2	58.90	✓
Accent Wordings.	per	56.50	✓
Rear RH Fender	Rejis	1703.20	+
Rear RH Fender Inner Trim	2nd	255.60	+
Rear RH Fender Inner Trim Clips.	m	30(SN)	+
Spare Tyre Panel Top Cover.	Delivered	265.30	—
Tools Tray Sponge.	all new	159.80	+
Rear Windscreen Moulding.	2nd	152.50	+
Rear Windscreen Sealant.	per	60(SN)	+

4952.20 S.N: 110
396176.

SMU 2562 S.

Panel Beating

Spray Painting.

Wiring.

To remove cruise sensor

To remove rear camera.

To spray tuff coat

To remove upholstery.

To transfer bootlid fittings.

To remove rear windscreen.

~~1500~~ 1200

~~1400~~ 1000

~~100~~ 30

~~100~~ 50

~~100~~ 50

~~150~~ 80

~~150~~ 60

~~150~~ 60 2530

180X.

total: 6601.76.

L/S: 5.2K

07 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: