

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 21 Sep 2022

Preliminary Advice

Insured Vehicle No	: SNC1859B		
TP Vehicle No	: SMU2562S	Accident Date	: 18/06/2022
Make	: HYUNDAI ACCENT (RB)	Assignment Date	: 20/06/2022
Date of Inspection	: 20/06/2022	Est. Duration of Repair	: 07 DAYS
Inspection At	: ONE GARAGE PTE LTD (HQ) 8 KAKI BUKIT AVE 4 #03-33 PREMIER @ K. BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,301.30
Revised Amount	:S\$	6,601.76
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,601.76
Lump Sum Repair	:S\$	5,200.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	32,650.00
Salvage Value	:S\$	
Margin for Repair	:S\$	49,350.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.