

TP MS16.

Celine.

SMU2562S. 2020 August.

Hyundai Accent. 1368cc

KMHCU41BTKU481927

Rear Number Plate.	} NP Mer	30(SN) X
Rear Number Plate Holder		30(SN) X.
Rear Bumper Deformed		545.30 ✓
Rear Bumper Clips. Mer		30(SN) ✓
Rear Bumper Side Holder x 02	2 pc	44.8 x 2 = 89.60 ✓ 154.60
Rear Bumper Reflector x 02	RH cml d	154.6 x 2 = 309.20 154.60
Rear Bumper Reinforcement	Cml d	376.50 ✓
Rear Bumper Reinforcement Bracket Upper x 02	RH and	25 x 2 = 50 25
Rear Bumper Reinforcement Bracket Lower x 03.	1 piece d	25 x 3 = 75 25
Tailcap x 02	RH cml d	388.4 x 2 = 776.80 388.40
Tailcap Panel RH.	Dented	278.40 ✓
Reverse Sensor x 04	2 pieces dml d	185 x 4 = 740 370
Reverse Sensor Holder x 04. Mer		25 x 4 = 100 ✓
Rear End Panel.	Dented	499.30 ✓

SMU25625.

Rear End Panel Top Garnish.	Rebrand	125.50	✓
Rear End Panel Top Garnish Clips.	m	20(SN)	✓
Rear End Panel Sealant	m	60(SN)	✓
Bootlid	Dented	1225.90	✓
Bootlid Lock	2nd	175.40	✓
Bootlid Weatherstripe.	lt	192.60	✓
Hyundai Logo.	2	58.90	✓
Accent Wording.	per	56.50	✓
Rear RH Fender	Regris	1703.20	+
Rear RH Fender Inner Trim	2nd	255.60	+
Rear RH Fender Inner Trim Clips.	m	30(SN)	+
Spare Tyre Panel Top Cover	Dented	265.30	✓
Tools Tray Sponge.	1st run	159.80	+
Rear Windscreen Moulding.	2nd	152.50	+
Rear Windscreen Sealant.	per	60(SN)	+

4952.20 S.N: 110
396176.

SMU 2562 S.

Panel Beating

Spray Painting.

Wiring.

To remove cruise sensor

To remove rear camera.

To spray tuff coat

To remove upholstery.

To transfer bootlid fittings.

To remove rear windscreen.

~~1500~~ 1200

~~1400~~ 1000

~~100~~ 30

~~100~~ 50

~~100~~ 50

~~150~~ 80

~~150~~ 60

~~150~~ 60 2530

180X.

total: 6601.76.

L/S: S.2K

07 Day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: