

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22005844/KQY3Q2**Date:** 08/11/2022**REFERENCE**

Insured/Claimant: Eng Cher Suah Policy No: DMPCSNW00187612101

Date of Loss: 15/06/2022 Nature of Claim: OD Claim No: SNM22D204254/C01/TAYHP

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLL5425U**

Make &amp; Model: LAND ROVER RANGE ROVER EVOQUE, 2.0 TSS (A)

Engine No: 090614051842204PT

Reg. Date: 27/10/2015 (Man. Year: 2015)

Chassis No: SALVA2AG3FH046158

Colour: White

Odometer: 164124 km

Engine Capacity: 1999 cc

Market Value/New Car Price: S\$108,000.00

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 235/60 R18

Rear Tyre Size: 235/60 R18

Front Left Side: Continental 4 mm

Rear Left Side: Continental 5 mm

Front Right Side: Continental 4 mm

Rear Right Side: Continental 5 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,152.00	4,932.00	1,220.00	19.83
Miscellaneous Items	220.00	220.00	0.00	0.00
Labour	436.80	709.80	-273.00	-62.50
Paintwork Labour	625.70	691.92	-66.22	-10.58
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,434.50</b>	<b>6,553.72</b>	<b>880.78</b>	<b>11.85</b>
<b>- Excess (\$\$)</b>	0.00	250.00	-250.00	
<b>(\$\$)</b>	7,434.50	6,303.72	1,130.78	15.21
<b>+ GST 7.00/7.00% (\$\$)</b>	520.42	441.26	79.16	15.21
<b>Nett Amount (\$\$)</b>	<b>7,954.92</b>	<b>6,744.98</b>	<b>1,209.94</b>	<b>15.21</b>

**INSPECTION**

Date of Assignment: 20/06/2022 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

Date Inspected: 21/06/2022 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

Estimated Period of Repair: 4.0 days 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 08 Nov 2022)

**Parts:** M1-SUV    LAND ROVER RANGE ROVER EVOQUE 2.0 TSS (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's    (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLL5425U)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		5,367.00 F	*4,147.00 F
<b><u>Supplementary #1</u></b>						
2	1		*CTR FRT BUMP BRACKET	Cracked	260.00 F	*260.00 F
3	1		*PARKING SYS SENSOR 1	Shorted	190.00 F	*190.00 F
4	1		*L/F W-HOUSE CVR FRT	Missing	210.00 F	*210.00 F
5	1		*L/F BUMPER BRACKET	Cracked	30.00 F	*30.00 F
6	1		*OIL COOLER CVR PANEL	Necessary	95.00 F	*95.00 F

F=Franchise part.

**Total Parts (S\$)**    **6,152.00**    **4,932.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Extra	220.00	220.00
Sub Total (\$\$)			220.00	220.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Including Material	New	625.70	691.92
<u>Labour Items</u>				
2	Total of Labour	New	436.80	709.80
Gross Labour Cost (\$\$)			1,062.50	1,401.72

Report was unsubmitted during this print-out.

< END OF ESTIMATES >