

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 09 Sep 2022

Preliminary Advice

Vehicle No	: SLL5425U	Accident Date	: 15/06/2022
Make	: LAND ROVER RANGE ROVER EVOQUE	Policy No.	: DMPCSNW00187612101
Assignment Date	: 20/06/2022	Excess	: S\$250.00
Date of Inspection	: 21/06/2022	Est. Duration of Repair	: 4
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,434.50	(Estimate \$6,649.50 + Supplementary \$785.00)
Revised Amount	:S\$	6,553.72	(Inclusive of supplementary)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	6,553.72	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 108,000.00
COE / PARF Rebate	:S\$ 65,088.00
Salvage Value	:S\$
Margin for Repair	:S\$ 42,912.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approve on supplementary.