

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS / GA122005850 / 4943**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

VDU7375

at Workshop m/s

of

Insured:

G3F551X

Policy No.

Claims No.

CLM01VC00004184

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

RM 95

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

VDU7375

Yr Regn:

30/09/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make:

NISSAN X-trail

c.c

1997

Colour

Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

86315

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/65R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

16/06/22

D.O.I.

22/06/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/7/22 2/5 @ 7800 informed yan hong (Red & 6903.79, 47%)

Date/Time, File Pass to?

☐

Preli. Report

20/7 2/5☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) ___ S + RS, ___ SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

TP

Lump Sum / I.B.I. (\$

7800

TOTAL

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

09-07-22

Date Of Accident : 16-06-22

OUR REF : VDU 7375/T/22

Tan Kok Kiang

C/o No. 1 Kaki Bukit Ave 6

#02-34

Singapore 417883

Not Authorized
LH
22/06/22
2/5 \$7800
4 days.

ESTIMATE BILL ON VEH. NO. : VDU 7375

MODEL : NISSAN X-TRAIL

CHASSIS NO. : PN8JAAT32TCA51266

NETT ITEM

Tail Gate	22/wereb	45/5	4,818.00	
Tail Gate Weatherstripe	11		154.90	X
Tail Gate Emblum "X-Trail"	11		121.00	✓
Tail Gate Badge	11		84.90	X
Tail Gate Stopper	11		17.10	X
Rear Bumper	De		762.40	✓
Rear Bumper Lower Bracket	3uf	580.10	860.70	✓
Rear Bumper Side Retainer	11s 3uf	2pcs @ 58.80	117.60	1PC
Rear Bumper Reflector LH	11		68.10	X
Rear Bumper Reinforcement	3uf	533.80	655.80	✓
Rear Bumper Reinforcement Bracket	11s 3uf 0/5 11	2pcs @ 215.2	430.40	1PC
Rear Bumper Chorme Moulding	11		188.50	✓
Rear Blind Spot Sensor LH	11	1545.00	1,900.00	✓
Rear Blind Spot Sensor Bracket	3uf		50.00	✓
Rear Bumper Clips	11	8pcs @ 6.50	52.00	✓
Tail Gate Outer Opener Sensor	11		79.80	X
Tail Gate Outer Opener Sensor Holder	11		160.00	X

Tail Gate Centrol Unit	11		675.10	X
Tail Gate Outer Keyless Sensor	11		88.70	X
Rear End Panel	R		492.30	X
Rear End Panel Top Trim	11		98.80	X
Rear End Panel Top Trim Clips	11	4pcs @ 6.50	26.00	X
Rear Windscreen Glass Clips	11	14pcs @ 6.50	91.00	X
			11,993.10	
10% Less Discount			1,199.31	
			10,793.79	

SPECIAL NETT ITEM

Rear Bumper Center Lamp	one		120.00	/
Rear Bumper Parking Sensor	shell		300.00	200
Rear Windscreen Glass Sealant	1ea		60.00	40
Rear Windscreen Glass Inner Seal	1ea		50.00	40

LABOUR CHARGE

To check wiring System		80.00	20
To remove & refixx reverse sensor		120.00	50
To remmove & refix tail gate mechanism		250.00	60
To remove & refix tail gate windscreen glass		180.00	120
To respray affected areas		1,200.00	600
To reset electrical module system		450.00	200
To renew damaged parts, straighten & repair and aligned all parts		1,100.00	550

TOTAL :	14,703.79
GST 7% :	1,029.27
AMOUNT DUE :	15,733.06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

9-8021-80
107
7759.62
400
1602
9759.62
7807



SINGAPORE POLICE FORCE



T/20220616/7034

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20220616/7034

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/06/2022 18:13	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: TAN KOK KIANG			Address: 15 JALAN PALMA MERAH 4 TAMAN DATO CHELLAM 81800		
ID Type / ID No.: FIN NO / F7108348U			Contact No.: Home/Office: Mobile: 93545591		
Nationality: MALAYSIAN			Email: kkpautan@gmail.com		
Sex: Male	Age: 49	Date of Birth: 13/03/1973	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: CONSTRUCTION WORKER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 16/06/2022 13:32	Type of Location: SLIP ROAD
Location: YIO CHU KANG SLIP ROAD TOWARDS HOUGANG AVE 3				
Weather: Raining		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of
GBF551X	Van					0
VDU7375	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20220616/7034

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20220616/7034

CONTINUATION OF REPORT

Driver				
Name	TAN KOK KIANG		ID No.	F7108348U
Related Vehicle	VDU7375 (Car)		Contact No.	93545591
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	16/06/2022		Date	NIL
No. of Days granted Medical Leave	03	Degree of	Slight	

Brief Details.

ON 16/06/2022 @ ABOUT 1332HRS, I WAS DRIVING MY CAR (VDU7375 - NISSAN X-TRAIL) FROM YIO CHU KANG ROAD. UPON REACHING THE WAY EXIT TO HOUGANG AVE 3, THE VEHICLE IN FRONT OF ME STOPPED TO GIVE WAY TO THE ONCOMING TRAFFIC FROM MAJOR ROAD. SO I ALSO SLOWED DOWN AND STOPPED IN TIME, SUDDENLY I FEEL AN IMPACT IN TIME FROM BEHIND AND I REALISED THAT VAN (GBF551X) COULD NOT STOP IN TIME AND COLLIDED ONTO MY CAR'S REAR PORTION, THE VAN DRIVER STOPPED AND APOLOGISED TO ME AND SAID THAT HE COULDN'T BRAKE IN TIME. I FEEL PAIN AND DISCOMFORT AFTER ACCIDENT IMPACT AND SO I WENT TO RESERVOIR ROAD CLINIC & SURGERY PTE LTD AND WAS GIVEN 3 DAYS MC, HENCE, I DO NOT HAVE ANY FOOTAGE OF THE ACCIDENT. I EXCHANGED PARTICULARS WITH THE VAN DRIVER. ONLY I WAS INJURED. POLICE & AMBULANCE NOT AT SCENE. THAT'S ALL.