

AutoSoon Pte Ltd

176 Siang Ming Drive #01-10
 Sin Ming AutoCare Singapore 575721
 Tel No. : +65 64526657 Fax No. : +65 64514618
 E-Mail : autosoon1@gmail.com
 Fax Reg. No. : 200709808N Buss. Reg. No. : 20709808N

BOO WING HOCK
 31k 676A, Jurong West St 64
 #06-259
 Singapore 641676

Contact : 9763 7619

Estimate : ES000596

Date : 23/05/2022
 Vehicle Num. : EQ 1101 L
 Make/Model : TOYOTA CAMRY HYBRID 2.5G CVT-2020
 Chassis/Eng# : JTNB23HK703035249
 Accident Date : 23/05/2022
 Claim No. : TP: China TaiPing_FTA
 Reference : TP/04/05/22
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.	1	Radiator grille assy <i>CR</i>		399.63
2.	1	Radiator grille assy securing clips kit <i>an</i>		50.00
3.	1	Radiator grille inner garnish <i>Xan</i>		235.30X
4.	1	Bumper facial <i>de</i>		552.65
5.	1	Bumper clip and mounting gromet <i>an</i>		80.00
6.	1	Bumper sponge <i>Xan</i>		168.30X
7.	1	Bumper lower sponge <i>Xan</i>		135.30X
8.	1	Bumper lower grille <i>CR</i>		181.96
9.	10	Bumper lower grille clip <i>an</i>		80.00
10.	1	O/s bumper retainer assy <i>CR</i>		131.68
11.	1	O/s parking sonar sensor assy <i>an</i>		396.24
12.	1	O/s parking sonar sensor bezel <i>Xan</i>		36.53X
13.	1	O/s head lamp assy <i>de</i>		2,208.74
14.	1	O/s head lamp lower stay <i>CR</i>		68.00
15.	1	O/s head lamp support panel <i>Xan</i>		231.80X

List Total S\$:

10.00% Discount S\$:

4,956.13

495.61

4,460.52

LABOUR :

1	To rewire affected section and refocus head lamp beam	80.00	80.00 <i>30</i>
1	To putty and respray affected section in repair.	880.00	880.00 <i>250</i>
1	To undersealing damaged panels with anti rust	150.00	150.00 <i>Xan</i>
1	To remove and replace damaged part, panel beat radiator	680.00	680.00 <i>250</i>

CONTINUE / ...

AutoSoon Pte Ltd

Page 2 / 2

176 Sin Ming Drive #01-10

Sin Ming AutoCare Singapore 575721

Tel No. : +65 64526657 Fax No. : +65 64514618

E-Mail : autosoon1@gmail.com

Tax Reg. No. : 200709808N Buss. Reg. No. : 20709808N

SOO WING HOCK

31K 676A, Jurong West St 64

#06-259

Singapore 641676

Contact : 9763 7619

Estimate : ES000596

Date : 23/05/2022

Vehicle Num. : EQ 1101 L

Make/Model : TOYOTA CAMRY HYBRID 2.5G CVT-2020

Chassis/Eng# : JTNB23HK703035249

Accident Date : 23/05/2022

Claim No. : TP: China TaiPing_FTA

Reference : TP/04/05/22

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1

support and head lamp panel include realign bumper in repair

To use Toyota computer platform to check/go on line to activate millimeter radar and parking sonar sensor

500.00

~~500.00~~ 100

Labour Total S\$:

2,290.00

3111.67

630.00

3741.67

20%

2993.34

\$3000.00 / 3 days

Rasul

Hy 90010068

3 days

4/8

24/06/22 @ 1520

Resurvey after repair

E. & O.E.

Total S\$:

6,750.52

for AutoSoon Pte Ltd

Kindly note above mentioned parts are visible quoted, we reserve our right to submit further quote if further parts are found damaged while undergoing repair.

Date Survey:

Surveyor Name:

Co Name:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: