

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10

Sin Ming AutoCare Singapore 575721

Tel No. : +65 64526657 Fax No. : +65 64514618

E-Mail : autosoon1@gmail.com

Tax Reg. No. : 200709808N Buss. Reg. No. : 20709808N

SOO WING HOCK

Blk 676A, Jurong West St 64

#06-259

Singapore 641676

Contact : 9763 7619

Estimate : ES000596

Date : 23/05/2022

Vehicle Num. : EQ 1101 L

Make/Model : TOYOTA CAMRY HYBRID 2.5G CVT-2020

Chassis/Eng# : JTNB23HK703035249

Accident Date : 23/05/2022

Claim No. : TP: China TaiPing_FTA

Reference : TP/04/05/22

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	Radiator grille assy		399.63
2.	1	Radiator grille assy securing clips kit		50.00
3.	1	Radiator grille inner garnish		235.30
4.	1	Bumper facial		552.65
5.	1	Bumper clip and mounting gromet		80.00
6.	1	Bumper sponge		168.30
7.	1	Bumper lower sponge		135.30
8.	1	Bumper lower grille		181.96
9.	10	Bumper lower grille clip	8.00	80.00
10.	1	O/s bumper retainer assy		131.68
11.	1	O/s parking sonar sensor assy		396.24
12.	1	O/s parking sonar sensor bezel		36.53
13.	1	O/s head lamp assy		2,208.74
14.	1	O/s head lamp lower stay		68.00
15.	1	O/s head lamp support panel		231.80
List TotalS\$:				4,956.13
10.00% Discount S\$:				495.61
				4,460.52
LABOUR :				
1		To rewire affected section and refocus head lamp beam	80.00	80.00
1		To putty and respray affected section in repair.	880.00	880.00
1		To undersealing damaged panels with anti rust	150.00	150.00
1		To remove and replace damaged part, panel beat radiator	680.00	680.00

CONTINUE / ...

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10

Sin Ming AutoCare Singapore 575721

Tel No. : +65 64526657 Fax No. : +65 64514618

E-Mail : autosoon1@gmail.com

Tax Reg. No. : 200709808N Buss. Reg. No. : 20709808N

SOO WING HOCK

Blk 676A, Jurong West St 64

#06-259

Singapore 641676

Contact : 9763 7619

Estimate : ES000596

Date : 23/05/2022

Vehicle Num. : EQ 1101 L

Make/Model : TOYOTA CAMRY HYBRID 2.5G CVT-2020

Chassis/Eng# : JTNB23HK703035249

Accident Date : 23/05/2022

Claim No. : TP: China TaiPing_FTA

Reference : TP/04/05/22

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1		support and head lamp panel include realign bumper in repair To use Toyota computer platform to check/go on line to activate millimeter radar and parking sonar sensor	500.00	500.00
		Labour Total S\$:		2,290.00

E. & O.E.

Total S\$:

6,750.52

for AutoSoon Pte Ltd

Kindly note above mentioned parts are visible quoted, we reserve our right to submit further quote if further parts are found damaged while undergoing repair.

Date Survey:

Surveyor Name:

Co Name: