

ASS. REC. BY: Steve

CS/FCI 22005852/E493

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. D22001849MFCVT
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SM4825E Yr Regn: 31/8/70
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW 216 c.c. 1899
 Colour: White A/C: Insured / Std / Nil / NA
 Sp. Reading: 17754 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: WBAGV120518R76080
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55 R17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /
 TOYO / YOKO or . _____
 Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 13/6/72 D.O.I. 24/6/72
 Survey held at BIS
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear RH
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MY-1081</u>
28/06/22	@6.19pm revised to FCI by email.

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.S. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927
BIS Automobiles Pte Ltd
Co. Reg. No. 201908617D, GST Reg. No. 201908617D



ESTIMATES

Estimate No. : 21998926
Date Estimated : 15/06/2022
Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -
Mr. GOH BENG KIAT

- ACCOUNT -
MS FIRST CAPITAL INSURANCE

Motor Claims Department

REGN. NO.
SMU8215E

CHASSIS NO.
5R76080

REGN. DATE
31/8/2020

MODEL
216

DESCRIPTION	ORIGINAL PRICE	NETT
To replace rear bumper and attachments, rear RH fender include making good the rear RH door and knocking out dents caused by the accident	3600	6,480.00
To spray paint rear bumper, rear RH fender, RH roof frame, RH rocker panel and rear RH door	3300	3,650.00
To supply rear RH wheel rim	X	TBA
To supply rear RH tyre	X	TBA
To replace rear RH tyre and wheel rim include wheel balancing	80	100.00
To conduct checks on steering geometry including wheel alignment in accordance with BMW specifications	360	450.00
To transfer PDC assembly from old to new bumper include reconnecting to new bumper and conducting checks for proper function	180	225.00
To remove and install Rear vehicle quarter glass (fixed) to facilitate repairs include conducting water leak tests	180	225.00
To remove and install Rear hat-tray, rear seats, carpet and roof top lining to facilitate repairs	576	720.00
To remove and install Rear boot compartment carpet and garnish to facilitate repairs	180	225.00
To remove and install fuel tank to facilitate repairs include conducting checks for leak and function (For cut panel)	360	450.00
To reconnect all electrical components and wirings at the	280	350.00

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927
BIS Automobiles Pte Ltd
Co. Reg. No. 201908617D, GST Reg. No. 201908617D



ESTIMATES

Rear RH section include conducting checks for proper function (For cut panel)

To carry out body cavity preservation (For cut panel)	280	450.00
To carry out Diagnostic Tests	490	500.00
Sundries	120	150.00

DESCRIPTION	UNIT PRICE	QTY	NETT
36 11 6856087 Disc wheel, light alloy, O <i>/ CUT</i>	977.35	1.00	977.35
36 13 6850834 Hub cap with chrome edge <i>X</i>	31.30	1.00	31.30
41 00 7436182 Right rear side panel <i>/ DD</i>	1,496.05	1.00	1,496.05
83 19 0301421 Blind rivet N3 <i>/ N/C</i>	0.55	8.00	4.40
07 14 7206525 Blind rivet nut with coll <i>/ N/C</i>	5.55	1.00	5.55
83 19 5A59935 Body adhesive K5 <i>/ N/C</i>	353.50	3.00	1,060.50
83 19 2158654 Body adhesive K5 (50 ml) <i>/ N/C</i>	121.90	1.00	121.90
83 12 0390086 Cavity protection wax <i>/ N/C</i>	18.45	1.00	18.45
83 19 2211217 Cleaner R1 (100ml) <i>/ N/C</i>	26.15	2.00	52.30
07 14 7350925 Collar screw <i>/ N/C</i>	3.65	1.00	3.65
51 16 1943122 Plastic cap nut with washer (d=18mm) <i>/ N/C</i>	0.85	4.00	3.40
07 14 7169847 Plastic cap nut with wa <i>/ N/C</i>	0.85	1.00	0.85
41 21 2460138 Positioning aid T-bolt <i>/ N/C</i>	5.90	1.00	5.90
83 19 2457307 Punch rivet N4 <i>/ N/C</i>	0.55	36.00	19.80
41 21 7407914 Reinforcement plate <i>?</i>	56.20	1.00	56.20
41 21 7407912 Reinforcement plate, sill, right <i>?</i>	56.45	1.00	56.45
41 21 7407914 Reinforcement plate, C-pillar <i>?</i>	56.20	1.00	56.20
41 21 7407916 Reinforcement plate, D-pillar, right <i>?</i>	64.20	1.00	64.20
51 37 7326174 Side window, fixed, rear right <i>/ N/C (photo)</i>	305.60	1.00	305.60
51 12 7466428 Trim strip, bumper, rear <i>?</i>	73.75	1.00	73.75
83 19 2289285 Repair kit, window glass <i>/ N/C</i>	131.55	2.00	263.10
51 12 7480324 Panel, bumper, primed, rear <i>/ CR4 (photo)</i>	1,050.55	1.00	1,050.55
51 12 7318754 Guide for bumper, side, right <i>?</i>	163.55	1.00	163.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal repair (e.g. welding) is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total Labour :	13,975.00
Total Parts :	5,891.00
Total Labour & Parts :	19,866.00
Deduction for Excess :	
Total Repair Costs less £	19,866.00
GST @7%:	1,390.62
Grand Total :	21,256.62