



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 1965C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FENDER FRONT LEFT	TO REPAIR SEE LABOUR	479.57	-
1	FENDER INNER SHIELD LH	SERVICEABLE	258.15	-
1	HEAD LAMP LEFT	CUT	1,521.50	1,392.70
1	HEAD LAMP CLIP LEFT	NOT NECESSARY	30.00	-
1	BUMPER FRONT	CRACKED / BUCKLED	745.55	523.50
1	BUMPER FOG LAMP GARNISH FRONT LH	SERVICEABLE	285.15	-
1	BUMPER FOG LAMP LH	SERVICEABLE	380.15	-
1	BUMPER REINFORCEMENT FRONT	TO REPAIR SEE LABOUR	450.15	-
1	BUMPER RETAINER FRONT LEFT	DISTORTED	40.17	40.17
1	SHOCK ABSORBER FRONT LEFT	SERVICEABLE	325.90	-
1	WHEEL RIM LH	SERVICEABLE	580.00	-
1	TYRE FRONT LEFT	SERVICEABLE	280.00	-
1	KNUCKLE ARM FRONT LEFT	SERVICEABLE	300.15	-
1	KNUCKLE ARM BEARING FRONT LEFT	NOT NECESSARY	161.07	-
1	LOWER ARM FRONT LEFT	SERVICEABLE	325.90	-
1	LOWER ARM BALL JOINT FRONT LEFT	SERVICEABLE	280.15	-
1	DRIVE SHIFT LH	TO REPAIR SEE LABOUR	1,050.60	-
1	HEADLAMP BRACKET	CRACKED	60.75	60.75
	LESS 20% DISCOUNT		-1,510.98	-403.42
			6,043.93	1,613.70
	<b><u>LABOUR</u></b>			
	TO DISMANTLE & REPLACE DAMAGE PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF FENDER FRONT LEFT, BUMPER REINFORCEMENT FRONT AND DRIVE SHIFT LH.		1,000.00	200.00
	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON AFFECTED PORTION.		900.00	400.00
	TO APPLY RUST PROOFING ON REPAIRED, REPLACED PANEL.	NOT NECESSARY	100.00	-
	TO REMOVE / REFIT UNDER CARRIAGE.	NOT NECESSARY	300.00	-

Report Ref No. CS/AGI22005853/Kqy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING FUNCTIONS.		80.00	20.00
	WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
			2,460.00	620.00
GRAND TOTAL			8,503.93	2,233.70
RECOMMENDED COST OF REPAIRS				2,233.70

Report Ref No. CS/AGI22005853/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.