



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111 X

ESTIMATE FOR SMM8770K

SOMPO INSURANCE SINGAPORE PTE LTD

MOTOR CLAIM DEPARTMENT
50 Raffles Place #03-03
Singapore Land Tower
Singapore 048623
64616555

WIP No

57554

Reg No/Reg Date

SMM8770K / 26/10/2017

Date In/Mileage

/ 0

Chassis No

WDD2130422A322786

Engine No

27492031189877

Make/Model

MB/MB E 200 2.0 SEDAN (W213) "EXCLUSIVE/

Colour/Trim

029 997 Kallaitte Gr/ 048 814 Leather Cap

Account No	Terms	Date/Time Printed	CSE	Operator
WT009122	Credit	15/06/2022/ 11:27		301 / Kerlyn Ong
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : 1900162701-02 // 14/06/2022

DRIVE IN/TP VEHICLE NO. : 15/06/2022 // SGU2378D - SOMPO

DATE IN/DATE SURVEY:

BY/AUTHORIZED ON :

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESpray REAR BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

M REAR BUMPER

1.00

1565.55 00.00

1565.55

M REAR BUMPER LOWER TRIM

1.00

336.57 00.00

336.57

M REAR BUMPER CHROME MOULDING

1.00

362.74 00.00

362.74

M REAR BUMPER BRACKET

1.00

82.93 00.00

82.93

M REAR DISTANCE SENSOR

2.00

195.43 00.00

390.86

M SPACER RING

2.00

7.10 00.00

14.20

M LH/ REAR BUMPER SIDE STABILITY

1.00

100.71 00.00

100.71

M RH/ REAR BUMPER SIDE STABILITY

1.00

100.18 00.00

100.18

M LH/ TAIL PIPE COVER

1.00

432.23 00.00

432.23

M LH/ TAIL PIPE COVER BRACKET

1.00

71.09 00.00

71.09

M LH/ REAR BUMPER CHROME MOULDING

1.00

152.14 00.00

152.14

M RH/ REAR BUMPER CHROME MOULDING

1.00

152.14 00.00

152.14

M CTR/ BASIC MOUNTING FOR BUMPER

1.00

134.29 00.00

134.29

M REAR CROSS MEMBER

1.00

943.74 00.00

943.74

Confirmed & accepted by

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

3 Lys

Nett

8,459.37

7% GST on

8459.37

592.16

Total Payable

9,051.53

LKK Auto Consultants hence notify

the Authorized signatory and company stamp

To resurvey before/after spray painting

To deliver this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be

required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur,

third party survey is on site. We confirm that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or

by bank transfer. In the event of a full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring

Supplement of the windscreen is subject to final approval from Insurance Company

Acknowledged by Repairer



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Page 1 of 1