



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMM8770K

SOMPO INSURANCE SINGAPORE PTE LTD

MOTOR CLAIM DEPARTMENT
50 Raffles Place #03-03
Singapore Land Tower
Singapore 048623
64616555

Vehicle & Document Information

WIP No **57554**
Reg No/Reg Date **SMM8770K / 26/10/2017**
Date In/Mileage **01/08/2022 / 52894**
Chassis No **WDD2130422A322786**
Engine No **27492031189877**
Make/Model **MB/MB E 200 2.0 SEDAN (W213) "EXCLUSIVE/"**
Colour/Trim **029 997 Kallaitte Gr/ 048 814 Leather Cap**

Account No	Terms	Date/Time Printed	CSE	Operator
WT009122	Credit	03/08/2022/ 16:34	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : 1900162701-02 // 14/06/2022 DRIVE IN/TP VEHICLE NO. : 15/06/2022 // SGU2378D - SOMPO DATE IN/DATE SURVEY: 01/08/2022 1000 // LKK - STEVE DIRECT SETTLEMENT : 20/06/2022 // SOMPO - MELVIN				
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				960.00
A BPIRES RESpray REAR BUMPER			0.05	800.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				120.00
X REAR BUMPER	1.00	1565.55	00.00	1565.55
X REAR BUMPER LOWER TRIM	1.00	336.57	00.00	336.57
X REAR BUMPER CHROME MOULDING	1.00	362.74	00.00	362.74
X SPACER RING	2.00	7.10	00.00	14.20
X LH/ TAIL PIPE COVER	1.00	432.23	00.00	432.23

Finalization

Confirmed & accepted by

Nett **4,971.29**
7% GST on **4971.29** **347.99**
Total Payable 5,319.28

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg