



漢強汽車修理

HANG KHIANG MOTOR WORKSHOP

BLK 3012, BEDOK IND. PARK E #01-2042,
BEDOK NORTH AVE 4 SINGAPORE 489978.
TEL 64412274 FAX 64421944
Regn. No: 341403/00L

TO: ECCS Insurance

Date: 23/6/2022

Estimated cost of repairs vehicle no. 6BH 2858M

Parts Supply

1 Pc. rear bumper
1 Pc. rear lamp Lh
1 Pc. rear lamp panel
1 Pc. rear tailgate

List Items

599.00
144.00
132.00
677.00
1,552.00
310.40
1,241.60

Less 20%

S. Net

1 Pc. rear tailgate "70" KM Sticker
1 Pc. rear tailgate "13" PAX Sticker
1 Pc. rear tailgate "KAO LEE" Sticker
1 Pc. rear no. plate

10.00
10.00
108.00
30.00

Labour charges.

To remove, cut out damaged portion, jack out,
straighten, panel beating, welding, align
and renew replace parts.

480.00

To putty and respray painting on affected areas.

400.00

To check wiring and lightings.

30.00

To anti rust on affected areas.

80.00

Total # 2,389.60