



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22005857/Kny3q2 Date: 12/08/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJB 5035M		Veh. Inspected	SKQ 2731R
Policy No.			Coverage (\$)	0.00
Claim No.	C10015752 /CD		Excess (\$)	0.00
Assign From	MAYBIE CHUA		Assign Date	20/06/2022
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY (A)		c.c	1998
Engine No.	HIDDEN		Year of Reg.	2014
Chassis No.	MR053BK5104023775		Colour	METALLIC BLACK
Odometer	30199 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	STANDARD ALLOY RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	YOKOHAMA	9 mm
	L/H Front Tyre	215/60 R16	YOKOHAMA	9 mm
	R/H Rear Tyre	215/60 R16	YOKOHAMA	9 mm
	L/H Rear Tyre	215/60 R16	YOKOHAMA	9 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	10/06/2022	Inspection Date	21/06/2022
	Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	