



TONG LUCK AUTO PTE LTD
160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722
Tel: 6250 0088 Fax: 6250 5545
Email: operation@tlauto.com.sg
GST No: 201700521W UEN No: 201700521W

M/S : RMG RENT-A-CAR PTE LTD
10 JALAN KILANG #01-01/02
ENTERPRISE CENTRE,
SINGAPORE 159410

TEL : 6235 1311

ATTN :

FAX : 6235 5256

YOUR REF NO : SJB5035M
CLAIM TYPE : THIRD PARTY
TP INS. CO. : AUTO & GENERAL INSURANCE (SINGAPORE) F
ACCIDENT DATE : 10/06/2022
TP VEH REG NO : SJB5035M

ESTIMATE

NO : QUOT202206-000050(00)
DATE : 20/06/2022
POLICY NO : SD22V05556/VPZ/R09
VEH REG NO : SKQ2731R
MAKE/MODEL : TOYOTA CAMRY 2.0 AUTO
CHASSIS NO : MR053BK5104023775
ENGINE NO : 1AZE292212
REG. DATE : 2014

PAGE: 1

Estimate Repair Cost to Vehicle No : SKQ2731R

Description	Quantity	Unit Price	Amount
LIST PRICE		S\$	S\$
1 Bonnet <i>1478.90</i>	1	1,478.90	1,478.90
2 Bonnet chrome	1	189.95	189.95
3 Headlamp assy - RH <i>1295.90</i>	1	1,295.90	1,295.90
4 Support panel	1	658.35	658.35
5 Support panel top garnish	1	229.95	229.95
6 Front bumper <i>599.85</i>	1	599.85	599.85
7 Front bumper reinforcement	1	399.50	399.50
8 Front bumper sponge	1	115.90	115.90
9 Front bumper side retainer - RH	1	112.40	112.40
10 Front bumper lower grille	1	199.80	199.80
11 Front bumper fog lamp - RH	1	359.60	359.60
12 Front bumper fog lamp cover - RH	1	75.90	75.90
			5,716.00
		Less 25%	1,279.02
			4,436.98
SPECIAL NET			
13 Front number plate	1	40.00	40.00
LABOUR			
14 To remove and refit air-con condenser, radiator and refill air-con gas	1	150.00	150.00
15 To remove and refit front bumper sensor	1	100.00	100.00
16 To check and rectify wiring system	1	80.00	80.00
17 To panel beat and straighten RH front fender, RH front chasis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
18 To putty and spray paint on affected areas	1	1,000.00	1,000.00
19 To apply rust-proofing on replaced and repaired panels	1	80.00	80.00
			2,410.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:
Date:

TOTAL S\$ 6,886.98

ADD GST @ 7% 482.09

GRAND TOTAL S\$ 7,369.07

SINGAPORE DOLLAR SEVEN THOUSAND THREE HUNDRED SIXTY-NINE AND CENTS SEVEN ONLY