




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO22005862/Kty3e2 Date: 23/06/2022 Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SGN 1644D	Veh. Inspected	GBG 5773J
	Policy No.	D21MTPV01015617	Coverage (\$)	0.00
	Claim No.	CMTD2202123/AGC	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	20/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTFAT35Y40K208714	Colour	BLUE
	Odometer	53483 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	BRIDGESTONE	6 mm
	L/H Front Tyre	195 R15X8	BRIDGESTONE	6 mm
	R/H Rear Tyre	155 R12X8 (D)	APLUS	9/9 mm
	L/H Rear Tyre	155 R12X8 (D)	APLUS	9/9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.			
5. General Information				
	Accident Date	17/06/2022	Inspect Date / Time	21/06/2022 (10:08 AM)
	Survey held at	KING'S AUTO REPAIR & SERVICE PTE LTD 176 SIN MING DRIVE, #02-10, SIN MING AUTOCARE, SINGAPORE 575721		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500-\$6,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	

Report Ref No. CS3/SMO22005862/Kty3e2

Inspected By

KSC

KONG SENG CHEONG

Licensed Appraiser

KK

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.