

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO SHD3384G
MAKE/REG 28.11.2019
MODEL TOYOTA PRIUS G4A

20.06.2022

CHIANG/NTUC

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER <i>de</i>		\$551.89
1	REAR UNDER COVER <i>XM</i>		\$654.96
1	REAR REINFORCEMENT <i>XM</i>		\$378.32
2	REAR BUMPER SIDE RETAINER RH/LH <i>1pc? rec</i>	\$112.70	\$225.40
1	REAR BUMPER REFLECTOR LH <i>XM</i>		\$55.00
10	REAR BUMPER CLIPS <i>an</i>	\$2.20	\$22.00
1	LH TAIL UPPER LAMP <i>con</i>		\$557.90
1	LH TAIL LOWER LAMP <i>con</i>		\$570.00
1	LH FENDER <i>repair</i>		\$992.04
1	LH FEDER SHIELD <i>XM</i>		\$134.20
SUB TOTAL			\$4,141.71
25.00%			\$1,035.42
DISCOUNTED TOTAL			\$3,106.28
1	PETROL SICKER <i>XM</i>		\$20.00
1	REVERSE SENSOR <i>XM</i>		\$135.70
			\$140.13
Labour Charge			
Panel Beating			
Spray Painting Charge			
Tuff Kote			
Remove and Rear upholstery			
Check Lighting			
Remove and Refix Reverse Sensor			
TOTAL LABOUR			\$1,920.00
ESTIMATE TOTAL			\$5,166.41
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

1360.86
1155.00
2515.86
20%
2012.69
4/5 - \$2,000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Date:

Paul
Hy 90010068
4 days
4/5
20/06/22 @ 1/620
Reey after repair