



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22005865/Kny3q2	
			Date: 15/09/2022	
			Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SGN 1644D	
	Policy No.	Coverage (\$)	0.00	
	Claim No. CMTD2202123/AGC	Excess (\$)	0.00	
	Assign From GRACE TEO	Assign Date	21/06/2022	
2. Vehicle Particulars & Condition				
	Make & Model TOYOTA ESTIMA (A)	c.c	2362	
	Engine No. HIDDEN	Year of Reg.	2006	
	Chassis No. ACR500006494	Colour	METALLIC BLACK	
	Odometer 261284 KM	Steering	IN ORDER	
	Brakes IN ORDER	Modification	STANDARD ALLOY RIM	
	General GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/65 R17	MICHELIN	4 mm
	L/H Front Tyre	215/65 R17	MICHELIN	4 mm
	R/H Rear Tyre	215/65 R17	CONTINENTAL	5 mm
	L/H Rear Tyre	215/65 R17	CONTINENTAL	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date 17/06/2022	Inspection Date	21/06/2022	
	Survey held at LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
	A)THE MARKET VALUE IS S\$51,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	