

來發 (明記) 摩多有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0029628
Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

Page 1 of 4
Your ref. D21MTPV01015617
Job No. 72777
Our ref. 22.06.28
Payment
Date 20/6/2022

Attn

Vehicle No SGN 1644D
Vehicle Model : Toyota Estima
Accident on ... 17/6/2022

Not Authorized
Li Pay @ 5500/-
Recovery After Repair
7 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Supply of Parts:			
1.00	Pc	Radiator grille logo emblem	40.00		
1.00	Pc	Bonnet	200.00		<i>Ry 200.00 ✓</i>
1.00	Pc	Bonnet hinge LH	25.00		<i>Dr 25.00 ✓</i>
1.00	Pc	Bonnet hinge RH	25.00		<i>Dr 25.00 ✓</i>
1.00	Pc	Bonnet lock	45.00		<i>Ry 45.00 ✓</i>
1.00	Pc	Bonnet insulation	100.00		<i>Sm 100.00 X</i>
1.00	Pc	Front bumper	750.00		<i>Pr/CM 750.00 ✓</i>
1.00	Pc	Front bumper centre grille	60.00		<i>CM 60.00 ✓</i>
1.00	Pc	Front bumper top beam	50.00		<i>Ry 50.00 ✓</i>
1.00	Pc	Front bumper sponge	38.00		<i>CM 38.00 ✓</i>
1.00	Pc	Front bumper rubber stopper LH	5.00		<i>Mr 5.00 ✓</i>
1.00	Pc	Front bumper rubber stopper RH	5.00		<i>Mr 5.00 ✓</i>
5.00	Pcs	Front bumper clips	1.50		<i>Mr 7.50 ✓</i>
1.00	Pc	Front fog lamp LH	115.00		<i>Ry 115.00 X</i>
1.00	Pc	Front fog lamp RH	115.00		<i>Sm 115.00 X</i>
1.00	Pc	Front fog lamp bulb RH	18.00		<i>KMA 18.00 X</i>
1.00	Pc	Front headlamp LH	700.00		<i>Br 700.00 ✓</i>
1.00	Pc	Front headlamp RH	700.00		<i>Br 700.00 ✓</i>
1.00	Pc	Front signal lamp bulb LH	6.00		<i>Sm 6.00 X</i>

拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。
还有先进的 SAICO Deluxe 喷漆烘炉。

Services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0029628
Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

Page 2 of 4
Your ref. D21MTPV01015617
Job No. 72777
Our ref. 22.06.28
Payment
Date 20/6/2022

Attn

Vehicle No SGN 1644D
Vehicle Model : Toyota Estima
Accident on ... 17/6/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Radiator grille	160.00		CM 160.00
1.00	Pc	Radiator grille logo emblem	40.00		Mc 40.00
5.00	Pcs	Radiator grille clips	1.50		Mc 7.50
1.00	Pc	Radiator grille top cover	90.00		CM 90.00
6.00	Pcs	Radiator grille top cover clips	2.00		Mc 12.00
1.00	Pc	Front support panel (centre)	110.00		BT 110.00
1.00	Pc	Front headlamp panel LH	100.00		BT 100.00
1.00	Pc	Front headlamp panel RH	100.00		BT 100.00
1.00	Pc	Radiator	500.00		PZ 500.00
1.00	Pc	Radiator cowl	110.00		CM 110.00
1.00	Pc	Radiator fan blade	60.00		in 60.00
1.00	Pc	Radiator fan motor	170.00		in 170.00
1.00		Radiator coolant - 4 litres	22.00		Mc 22.00
1.00	Pc	Washer tank	60.00		in 60.00
1.00	Pc	Aircon condenser	380.00		PZ 380.00
1.00	Pc	Aircon fan blade	75.00		in 75.00
1.00	Pc	Aircon fan motor	170.00		in 170.00
1.00	Pc	Battery top bracket	25.00		BT 25.00
1.00	Pc	ECU	1,200.00		PZ 1,200.00

司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理
还有先进的 SAICO Deluxe 喷漆烘炉。
services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the suppo
system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAIC
e oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0029628
Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

Page 3 of 4
Your ref. D21MTPV01015617
Job No. 72777
Our ref. 22.06.28
Payment
Date 20/6/2022

Attn

Vehicle No SGN 1644D
Vehicle Model : Toyota Estima
Accident on ... 17/6/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		Total amount of parts supplied - S\$6,356.00			
1.00		10% of parts supplied:	635.60		635.60
		Special nett item:			
1.00	Pc	Front number plate	35.00		35.00 ✓
		Labour & Misc:			
1.00		To check/erase fault codes	80.00		80.00 ✓
1.00		To remove + renew aircon condenser + refill gas	150.00		150.00 100%
1.00		To reprogramme ECU	350.00		350.00 X
1.00		To straighten front body including cutting and welding; to renew of parts	650.00		650.00 600%

Work done/Parts replaced not by
the following:
- To remove/renew/repair spray painting
- To replace/renew/repair during recovery
- Parts price is subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplier must be insured
- Is subject to final approval from Insurance Company

Acknowledged by:
Signature:
Date:

Sub-Total
GST 7.00%
Total

最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
先进的 SAICO Deluxe 喷漆烘炉。
ices include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support
em to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO
n heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0029628
Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

Page 4 of 4
Your ref. D21MTPV01015617
Job No. 72777
Our ref 22.06.28
Payment
Date 20/6/2022

Attn

Vehicle No SGN 1644D
Vehicle Model : Toyota Estima
Accident on ... 17/6/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To spray paint (including blend front fender LH & RH)	800.00		800.00 <i>720</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub-Total
GST 7.00%
Total

9,056.60
633.96
S\$ 9,690.56

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."