

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 31 Aug 2022

Preliminary Advice

Insured Vehicle No	: XE6935C	Accident Date	: 18/06/2022
TP Vehicle No	: SNG3373B	Assignment Date	: 20/06/2022
Make	: HYUNDAI I30 PDE	Est. Duration of Repair	: 5
Date of Inspection	: 22/06/2022		
Inspection At	: J.E.W MOTOR PTE LTD (HQ) 60 JALAN LAM HUAT #03-72 CARROS CENTER SINGAPORE 737869		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,362.95
Revised Amount	:S\$	5,850.65
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,850.65
 Lump Sum Repair	 :S\$	 4,650.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.