



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile          |  |  |   |            |
|--|--|--|---|------------|
| HL ASSURANCE PTE LTD<br>11 KEPPEL ROAD<br>#11-01 ABI PLAZASINGAPORE 089057 |  |  | Ref: CS/HLA22005870/Uvy3<br>Date: 21/06/2022<br>Code: HLA |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                          |  |  |   |            |
|  | Insured Veh.   | SLL 6787T  | Veh. Inspected  | SMJ 7801C  |
|  | Policy No.   | MP318344   | Coverage (\$)   | 0.00       |
|  | Claim No.  | MPC03504/LJ  | Excess (\$)   | 0.00       |
|  | Assign From  | LURENE JAW   | Assign Date   | 21/06/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>                              |  |  |   |            |
|  | Make & Model   |  | c.c   | 0          |
|  | Engine No.   | HIDDEN   | Year of Reg.  |            |
|  | Chassis No.  |  | Colour  |            |
|  | Odometer   | -  | Steering  |            |
|  | Brakes   |  | Modification  |            |
|  | General  |  |   |            |
| <b>3. Conditions of Tyres</b>  |  |  |   |            |
|  |  | Size   | Make  | Balance    |
|  | R/H Front Tyre   |  |   | mm         |
|  | L/H Front Tyre   |  |   | mm         |
|  | R/H Rear Tyre  |  |   | mm         |
|  | L/H Rear Tyre  |  |   | mm         |
| <b>4. Description of Damages</b>   |  |  |   |            |
|  |  |  |   |            |
| <b>5. General Information</b>  |  |  |   |            |
|  | Accident Date  | 18/06/2022   | Inspection Date   | 21/06/2022 |
|  | Survey held at   | PROGRESSIVE CAR CARE PTE LTD<br>BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716 |   |            |
| <b>5a. Remarks</b>   |  |  |   |            |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |   |            |