



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|--|-------------------------------|--------------------|
| STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705 | | | Ref: CS3/SMR22005877/Ety3e2-1 | |
| | | | Date: 22/06/2022 | |
| | | | Code: SMR | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| | Insured Veh. | SMB 1579B | Veh. Inspected | YN 5404R |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | BUS/04/22/5036 | Excess (\$) | 0.00 |
| | Assign From | JIMMY | Assign Date | 21/06/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | mitsubishi canter | c.c | 2998 |
| | Engine No. | HIDDEN | Year of Reg. | 2014 |
| | Chassis No. | FEB21EA00412 | Colour | WHITE |
| | Odometer | 360414 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| | General | FAIR | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 195 R15C | GOODYEAR | 4 mm |
| | L/H Front Tyre | 195 R15C | GOODYEAR | 4 mm |
| | R/H Rear Tyre | 195 R15C | GOODYEAR | 4 mm |
| | L/H Rear Tyre | 195 R15C | GOODYEAR | 4 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 21/04/2022 | Inspection Date | 27/04/2022 |
| | Survey held at | RIGHT CLICK AUTOWORKS PTE LTD 7 SOON LEE STREET, #01-27, ISPACE, SINGAPORE 627608 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 3 Working Days | |