

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005883/EVY3Q2**Date:** 19/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00183312102
Claimant Vehicle No :	FBG7338U	Insured Vehicle No :	SLM2676B
Date of Loss:	12/01/2022	Nature of Claim:	TP
		Claim No:	SNM22D200345C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBG7338U		
Make & Model:	DUCATI 1199 PANIGALES, 1.2 ABS	Engine No:	ZDM1198WE008507
Reg. Date:	29/10/2012 (Man. Year: 2012)	Chassis No:	ZDMH800ABCB008353
Colour:	Red	Odometer:	17337 km
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70Z R17	Rear Tyre Size:	200/55Z R17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 0 mm	Rear Right Side:	Pirelli 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,931.30	2,301.90	6,629.40	74.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,582.00	2,400.00	182.00	7.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,513.30	4,701.90	6,811.40	59.16
+ GST 7.00/7.00% (S\$)	805.93	329.13	476.80	59.16
Nett Amount (S\$)	12,319.23	5,031.03	7,288.20	59.16

INSPECTION

Date of Assignment:	27/06/2022		
Date Inspected:	21/06/2022	Inspected At:	Wearnes automotive Pte Ltd (HQ) 45 LENG KEE ROAD Singapore 159103
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Jan 2023)	
Parts:	N/A	DUCATI 1199 PANIGALES 1.2 ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBG7338U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SHOCK ABSORBER	Broken	2,640.00 FS	*650.00 FS
2	1		*GEARCHANGE LEVE	Bent	178.20 FS	*178.20 FS
3	1		*COVER PEDAL	Necessary	12.90 FS	*12.10 FS
4	1		*WASHER	Necessary	1.30 FS	*1.20 FS
5	2		*O-RING	Necessary	0.80 FS	*0.60 FS
6	1		*PIN PEDAL	Necessary	8.60 FS	*8.20 FS
7	1		*BUSH	Not Necessary	6.60 FS	*- FS
8	1		*LEFT FOOTREST	Cut	63.70 FS	*63.70 FS
9	1		*SCREW TCEIF M5X	Not Necessary	2.50 FS	*- FS
10	1		*SCREW TCEIF M5X	Not Necessary	2.50 FS	*- FS
11	1		*FOOTREST PIN	Not Necessary	18.10 FS	*- FS
12	1		*CIRCLIP E-TYPE	Not Necessary	1.00 FS	*- FS
13	1		*COUNTERWEIGHT	Cut	51.80 FS	*51.80 FS
14	1		*HANDLEBAR TUBE	Bent	143.20 FS	*143.20 FS
15	1		*STEERING HEAD	Not Necessary	715.00 FS	*- FS
16	1		*CLAMP FRONT LH	Not Necessary	152.20 FS	*- FS
17	1		*CLAMP REAR	Not Necessary	130.20 FS	*- FS
18	1		*PIN	Not Necessary	16.00 FS	*- FS
19	1		*SPRING RING	Not Necessary	1.20 FS	*- FS
20	1		*FRONT LH PLAT	Not Necessary	258.60 FS	*- FS
21	1		*CLUTCH CONTROL	Cut	238.60 FS	*238.60 FS
22	1		*COVER FRAME LH	Not Necessary	547.60 FS	*- FS
23	1		*REAR -VIEW MIRRO	Not Necessary	391.20 FS	*- FS
24	1		*COMPLETE HEADLI	Not Necessary	1,369.00 FS	*- FS
25	1		*LEFT UPPER HALF	Not Necessary	1,019.20 FS	*- FS
26	1		*LEFT LOWER FAIR	Cut	827.00 FS	*827.00 FS
27	10		*WASHER	Not Necessary	7.00 FS	*- FS
28	1		*LEFT HOLDER	Cut	127.30 FS	*127.30 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **8,931.30** **2,301.90**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ACCIDENT DAMAGE ASSESSMENT	New	70.00	0.00
2	TOWING FROM AMK	New	42.00	0.00
3	TO REPLACE DAMAGED PARTS CAUS	New	2,400.00	2,400.00
4	ACCIDENT DAMAGE ASSESSMENT	New	70.00	0.00
Gross Labour Cost (\$\$)			2,582.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >