

Store (LKR)
21/6/22, 4:30pm

W R
P/P
L R L
2 Lyr

SERVICE ESTIMATE

96657 - L00027 SL: LIBERTY INSURANCE PTE LTD (DUCATI)

Mr Rodney Lopez
BLK 215 Ang Mo Kio Avenue 1
#10-907
Singapore
Singapore
Singapore 560215

Inv.No. . . : D 0 Page 1
Inv.date . . : 20/06/2022
WIP No. . . : 13413
Veh. In/Out: 15/02/2022 20/06/2022
*Tel.No. . . : Mobile: 90607903
Reg.No. . . : FBG7338U / PAN 1199
Reg.date . . : 29/10/2012
Mileage . . : 17,337
Chassis No.: ZDMHB00ABCB009353
Variant... : 1199PanigaleABS

Closed by . . . : Tony Alfred Desire D
Svc Consultant : Tony Alfred Desire D
Remarks : Mr Rodney Lopez

Op.No	Description	CCC Mech Qty	Price	Disc%	Pkg	Amount	G
NOTES	bike knock by a car stationary drop		0.00	0			S
DUCT-A	Accident Damage Assessment		70.00	X 0		70.00	S
000	Receive Pre-booked Customer		0.20	X 0		0.20	S
NOTES	Customer Highlights		0.00	0			S
NOTES	Workshop Highlights		0.00	0			S
006	Towing from AMK #2054		42.00	X 0		42.00	S
DUCT-A	Accident Damage Assessment		70.00	X 0		70.00	S
DUCT-S	Shock Absorber / BR		2640.00	0	650 ✓	2640.00	S
DUCT-1	To replace damaged parts		2400.00	✓ 0		2400.00	S
	GEARCHANGE LEVE / OT	1.0 EA	178.20			178.20	✓
	COVER PEDAL / MC	1.0 EA	12.90		12.10 ✓	12.90	S
	WASHER / n	1.0 EA	1.30		1.20 ✓	1.30	S
	O-RING / n	2.0 EA	0.40	0.30	0.60 ✓	0.80	S
	PIN PEDAL / n	1.0 EA	8.60		8.20 ✓	8.60	S
	BUSH / n X nn	1.0 EA	6.60			6.60	S
	LEFT FOOTREST / n	1.0 EA	63.70			63.70	✓
	SCREW TCEIF M5X / n X nn	1.0 EA	2.50			2.50	S
	SCREW TCEIF M5X / n X nn	1.0 EA	2.50			2.50	S
	FOOTREST PIN / n X nn	1.0 EA	18.10			18.10	S

SERVICE ESTIMATE

95257 - L00027 SL: LIBERTY INSURANCE PTE LTD (DUCATI)

Mr. Rodney Lopez
BLK 215 Ang Mo Kio Avenue 1
#10-907
Singapore
Singapore
Singapore 560215

Inv.No. ... : D 0 Page 2
Inv.date ... : 20/06/2022
WIP No. ... : 13413
Veh. In/Out: 15/02/2022 20/06/2022
*Tel.No. ... : Mobile: 90607903
Reg.No. ... : FBG7338U / PAN 1199
Reg.date ... : 29/10/2012
Mileage ... : 17,337
Chassis No.: ZDMH800ABC8008353
Variant... : 1199PanigaleA8S

Closed by : Tony Alfred Desire D
Svc Consultant : Tony Alfred Desire D
Remarks : Mr Rodney Lopez

Op.No	Description	CCC	Mach	Qty	Price	Disc%	Pkg	Amount G
	CIRCLIP E-TYPE	mc	X	1.0 EA	1.00			1.00 S
	COUNTERWEIGHT	CUT		1.0 EA	51.80			51.80 ✓
	HANDLEBAR TUBE	BT		1.0 EA	143.20			143.20 ✓
	STEERING HEAD	BT (phb)	X	1.0 EA nn	715.00			715.00 S
	CLAMP FRONT LH	BT (phb)	X	1.0 EA nn	152.20			152.20 S
	CLAMP REAR	BT (phb)	X	1.0 EA nn	130.20			130.20 S
	PIN	mc	X	1.0 EA nn	16.00			16.00 S
	SPRING RING	mc	X	1.0 EA nn	1.20			1.20 S
	FRONT L.H. PLAT	?	X	1.0 EA nn	258.60			258.60 S
	CLUTCH CONTROL	CUT		1.0 EA	238.60			238.60 ✓
	COVER FRAME LH	(Rear LH) X Rear		1.0 EA cut	547.60			547.60 S
	REAR-VIEW MIRRO	CUT	X	1.0 EA nn	391.20			391.20 S
	COMPLETE HEADLI	(Hardly cover) X Rear		1.0 EA cut	1369.00			1369.00 S
	LEFT UPPER HALF	CUT		1.0 EA	1019.20			1019.20 S
	LEFT LOWER FAIR	mc	X	1.0 EA nn	791.00		827 ✓	791.00 S
	WASHER	mc	X	10.0 EA nn	0.70			7.00 S
	Left Holder	CUT		1.0	127.30			127.30 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

DUCATI
SINGAPORE

Acknowledged by Repairer
Signature:

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 | ducati.enquiries@wearnes.com | +65 6430 4930
www.ducati.com.sg

Amount 11,350.20

GST @ 7% 794.51
Total Amount 12,144.71
Less Amt Paid 0.00
Nett Amount 12,144.71