

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jun 2022)
 Parts: M1-SUV TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Wah Hong Motors & Credit Pte Ltd/SMW1937R/20/06/2022 15:19
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper / BR	0.00	0.00	*280.00 F/
2	1		*Front bumper side retainer LH/RH @2*\$50 ? X nn	0.00	0.00	*100.00 F
3	1		*Center grille assy / CUT	0.00	0.00	*200.00 F/
4	1		*Rear door RH / nn	0.00	0.00	*580.00 F/
5	1		*Rear fender RH / nn	0.00	0.00	*580.00 F/
6	1		*Rear windscreen moulding / ncc	0.00	0.00	*60.00 F/
7	1		*Front bumper lower skirt / CUT	0.00	0.00	*170.00 F/
8	1		*Rear bumper (Repair refer to labor) X R	0.00	0.00	*-F
9	1		*Support panel (Repair refer to labor) X nn	0.00	0.00	*-F
Sub Total (\$\$)						1,970.00
+ Margin on L,N Items 5.00% (\$\$)						98.50
Total Parts (\$\$)						2,068.50

F=Franchise part.

Wah Hong Motors & Credit Pte Ltd/SMW1937R/20/06/2022 15:19. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LEK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	center grille clips <i>prc</i>	15 30.00
2	1	Front bumper clips <i>prc</i>	30 35.00
3	1	Rear fender sealant <i>prc</i>	40 50.00
Sub Total (\$\$)			85 115.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	900 1,000.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	800 1,000.00
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	30 60.00
4	To remove and refit/replace Front door RH fitting, trimmings, garnish, window glass and lock mechanism	New	30 100.00
5	To remove and refit rear seat in order to repair	New	30 100.00
6	To remove and refit/replace roots lining & upholster garnish	New	50 100.00
Gross Labour Cost (\$\$)			1840 2,360.00

*= 3888.50 L/S - 3110.80
= 3100*

Wah Hong Motors & Credit Pte Ltd/SMW1937R/20/06/2022 15:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*Stew (LKK)
21/6/22, 3.00pm*

*L/S
7 AL 17
7 L/S
OD - Not L
Excess - ?*