



FINALIZE

GST Ref. No: 20-0000274-Z

Vehicle No: SKL8302H
Chassis No: W0VZT6EC0J1068966
Engine No: T2172228HARX0754
Date of accident: 07/06/2022

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty.	Description	Price (SGD)
<u>1</u>	1	FRT BONNET	\$ 2,557.00
<u>2</u>	1	FRT BONNET LOCK	\$ -
<u>3</u>	1	FRT BONNET LOCK BRACKET	\$ 280.00
<u>4</u>	5	FRT BONNET INSULATOR CLIP	\$ -
<u>5</u>	1	FRT BUMPER	\$ 1,764.00
<u>6</u>	1	FRT BUMPER TOW COVER	\$ -
<u>7</u>	1	FRT BUMPER NUMBER PLATE BASE	\$ -
<u>8</u>	5	FRT BUMPER CLIP	\$ 32.50
<u>9</u>	1	FRT BUMPER SIDE RETAINER LH - GUIDE	\$ -
<u>10</u>	1	FRT BUMPER SIDE RETAINER RH - GUIDE	\$ -
<u>11</u>	1	FRT BUMPER BRACKET LH	\$ 172.00
<u>12</u>	1	FRT BUMPER BRACKET SUPORT LH	\$ 136.00
<u>13</u>	1	FRT BUMPER BRACKET RH	\$ 172.00
<u>14</u>	1	FRT BUMPER BRACKET SUPORT RH	\$ 136.00
<u>15</u>	1	FRT BUMPER BRACKET TOP CENTRE	\$ 284.00
<u>16</u>	1	FRT BUMPER PEDESTRIAN IMPACT SRS SENSOR	\$ 513.00
<u>17</u>	1	FRT BUMPER SPONGE	\$ 238.00
<u>18</u>	1	FRT BUMPER SPONGE SUPORT	\$ 238.00
<u>19</u>	1	FRT BUMPER REINFORCEMENT UPP - Crash Limiter	\$ 799.00
<u>20</u>	2	FRT BUMPER PARKING SENSOR	\$ -
<u>21</u>	1	FRT BUMPER BLIND SPOT SENSOR	\$ -
<u>22</u>	6	FRT BUMPER PARKING SENSOR SEAL	\$ 102.00
<u>23</u>	1	FRT BUMPER PARKING SENSOR WIRE HARNESS	\$ -
<u>24</u>	1	FRT GRILLE ASSY	\$ 1,590.00
<u>25</u>	1	FRT GRILLE LOGO	\$ 204.00
<u>26</u>	1	RH HEADLAMP	\$ -
<u>27</u>	1	LH HEADLAMP	\$ 5,404.00

<u>28</u>	1	RADIATOR SUPORT PANEL TOP GARNISH			\$	166.00
<u>29</u>	1	A/C WARNING LABEL			\$	27.00
<u>30</u>	1	RADIATOR SUPORT PANEL TOP			\$	-
<u>31</u>	1	A/C CONDENSER			\$	-
<u>32</u>	1	A/C CONDENSER SUPORT - Bracket			\$	-
<u>33</u>	1	A/C CONDENSOR AIR GUIDE LOW CENTRE			\$	-
<u>34</u>	1	A/C CONDENSER AIR GUIDE RH			\$	-
<u>35</u>	1	A/C CONDENSER AIR GUIDE LH			\$	150.00
<u>36</u>	1	ENGINE AIR INTAKE RESONATOR HOSE			\$	-
<u>37</u>	1	FRT RADAR MODULE			\$	3,369.00
<u>38</u>	1	FRT RADAR MODULE BRACKET			\$	273.00

Supplementary

<u>1</u>	1	ENGINE ROOM & BODY CHASSIS WIRE HARNESS		\$	7,335.00
<u>2</u>	1	FRT FORWARD CAMERA		\$	852.00
<u>3</u>	1	FRT FORWARD CAMERA BRACKET		\$	83.00
<u>4</u>	1	FRT BUMPER LOW CENTRE GRILLE		\$	266.00

Total: \$ 27,142.50
Less 10%: \$ 2,714.25
Parts Total: \$ 24,428.25

Labour

<u>No.</u>		Price (SGD)
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,300.00
<u>2</u>	Carry out spray painting on affected area	\$ 1,375.00
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00
<u>4</u>	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ -
<u>5</u>	To remove and refit radiator and conduct pressure test	\$ -
<u>6</u>	To conduct reset of ADAS	\$ 600.00
<u>7</u>	To conduct reset of engine light on	\$ 350.00
<u>8</u>	To refocus headlamp	\$ -
<u>9</u>	To remove and refit front sensor	\$ 60.00
<u>10</u>	To remove and replace engine room & body chassis wire harness	\$ 3,250.00

Labour Total : \$ 7,055.00

Other

No.		Price (SGD)			
1	1	FRT NUMBER PLATE			\$ 65.00

Other Total : \$ 65.00

Total : \$ 31,548.25

Excess: \$ 700.00

GST (7%) : \$ 2,467.86

Grand Total : \$ 33,316.11

Yours Faithfully,

Service Advisor

Tel: 68441985 Fax:68445185

Please check and finalize with me