



AUTO
GERMANY
PTE LTD

Repair Estimate



Date : 17.06.2022

Reference: OPEL
Make: INSIGNIA

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SKL8302H
CHASSIS NO.: W0VZT6EC0J1068966
ENGINE NO.: T2172228HARX0754

Name of insured : CHONG KHIN LUNG
Date of accident : 07/06/2022

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>Demolished</i>	\$ 2,557.00
2	1	FRT BONNET LOCK <i>new</i>	\$ 170.00
3	1	FRT BONNET LOCK BRACKET <i>3 x 1 Bert</i>	\$ 280.00
4	5	FRT BONNET INSULATOR CLIP <i>1 x 1 new</i>	\$ 32.50
5	1	FRT BUMPER <i>Demolished</i>	\$ 1,764.00
6	1	FRT BUMPER TOW COVER <i>new</i>	\$ 139.00
7	1	FRT BUMPER NUMBER PLATE BASE <i>new</i>	\$ 232.00
8	10	FRT BUMPER CLIP <i>new</i>	\$ 65.00
9	1	FRT BUMPER SIDE RETAINER LH - GUIDE <i>3 x 1</i>	\$ 151.00
10	1	FRT BUMPER SIDE RETAINER RH - GUIDE <i>1 x 1</i>	\$ 151.00
11	1	FRT BUMPER BRACKET LH <i>new</i>	\$ 172.00
12	1	FRT BUMPER BRACKET SUPORT LH <i>new</i>	\$ 136.00
13	1	FRT BUMPER BRACKET RH <i>new</i>	\$ 172.00
14	1	FRT BUMPER BRACKET SUPORT RH <i>new</i>	\$ 136.00
15	1	FRT BUMPER BRACKET TOP CENTRE <i>Bert</i>	\$ 284.00
16	1	FRT BUMPER PEDESTRIAN IMPACT SRS SENSOR <i>new</i>	\$ 513.00
17	1	FRT BUMPER SPONGE <i>new</i>	\$ 238.00
18	1	FRT BUMPER SPONGE SUPORT <i>new</i>	\$ 238.00
19	1	FRT BUMPER REINFORCEMENT UPP - Crash Limiter <i>new</i>	\$ 799.00
20	2	FRT BUMPER PARKING SENSOR <i>new</i>	\$ 788.00
21	1	FRT BUMPER BLIND SPOT SENSOR <i>new</i>	\$ 391.00
22	6	FRT BUMPER PARKING SENSOR SEAL <i>new</i>	\$ 102.00
23	1	FRT BUMPER PARKING SENSOR WIRE HARNESS <i>new</i>	\$ 331.00
24	1	FRT GRILLE ASSY <i>new</i>	\$ 1,590.00
25	1	FRT GRILLE LOGO <i>new</i>	\$ 204.00
26	1	RH HEADLAMP <i>3 x 1 new</i>	\$ 540.00
27	1	LH HEADLAMP <i>3 x 1 new</i>	\$ 540.00
28	1	RADIATOR SUPORT PANEL TOP GARNISH <i>Demolished</i>	\$ 166.00
29	1	A/C WARNING LABEL <i>new</i>	\$ 27.00
30	1	RADIATOR SUPORT PANEL TOP <i>new</i>	\$ 498.00
31	1	A/C CONDENSER <i>3 x 1 new</i>	\$ 1,658.00
32	1	A/C CONDENSER SUPORT - Bracket <i>new</i>	\$ 237.00

Auto Germany Pte Ltd
7 Ubi Close, Alpine Centre
Singapore 408604

Sales Tel: 6922-3288 Fax: 6922-3289
Service Tel: 6922-3282 Fax: 6922-3283
Parts Tel: 6922-3285 Fax: 6922-3286

Opel Passenger and Commercial Vehicles

Email: enquiry@autogermany.sg
Web: opel.com.sg

33	1	A/C CONDENSOR AIR GUIDE LOW CENTRE	new	\$	166.00	+
34	1	A/C CONDENSER AIR GUIDE RH	new	\$	148.00	+
35	1	A/C CONDENSER AIR GUIDE LH	new	\$	150.00	+
36	1	ENGINE AIR INTAKE RESONATOR HOSE	new	\$	304.00	+
37	1	FRT RADAR MODULE	new	\$	3369	+
38	1	FRT RADAR MODULE BRACKET	new	\$	273	+

Parts Total: \$ 14,989.50
Less 10%: \$ 1,498.95
Total: \$ 13,490.55

Reminded,
Adrian L,
11/11/22

FRONT Labour

No.	Labour Description	Price (SGD)	
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 3,900.00	1300
2	Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT SUPPORT PANEL, FRT FENDER LH, FRT FENDER RH, FRT DOOR RH, FRT DOOR LH	\$ 2,750.00	1375
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 220.00	120
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00	+
5	To remove and refit radiator and conduct pressure test	\$ 120.00	+
6	To conduct reset of ADAS	\$ 600.00	+
7	To conduct reset of engine light on	\$ 350.00	+
8	To refocus headlamp	\$ 80.00	+
9	To remove and refit front sensor	\$ 120.00	60

Labour Total: \$ 8,740.00

Others

No.	Other Description	Price (SGD)
1	FRT NUMBER PLATE	\$ 65.00

Other Total: \$ 65.00

TOTAL: \$ 22,295.55
GST (7%): \$ 1,560.69
GRAND TOTAL: \$ 23,856.24

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor

Adrian Lij
P/P 22/08/22
05 Days.
Excess \$700.
Not Authorized

562 830217

[illegible]