

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Lee

Date: 13 Oct 2022

Preliminary Advice

Insured : YP9633J

Vehicle No

TP Vehicle : SMH71Z
No

Accident Date : 19/06/2022

Make : MERCEDES-BENZ CLA45
AMG

Assignment Date : 23/06/2022

Date of : 22/06/2022
Inspection

Est. Duration of : 8
Repair

Inspection At : CS ONG AUTO PTE LTD (HQ)
BLK 10 ANG MO KIO IND PARK 2A #02-16 AMK AUTO POINT
SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 86,061.83

Revised Amount :S\$ 15,647.38

Check Items (Estimated) :S\$ 0.00

Total :S\$ 15,647.38

Lump Sum Repair :S\$ 12,500.00

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$

COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.