



Your Ref: SNM22D204283/C01/TANKW

Date: 03rd Jan 2023

Our Ref: CS/CTI22005901/Vcy3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Dear Sir / Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO: SNA 3394Y
ACCIDENT ON 18/06/2022**

Instruction was received from Ms Billy Tan to inspect the vehicle Reg. No. SNA 3394Y at the premises of M/s: Blk 14 Defu Lane 10 #01-410/412, Singapore 539195, Repairer: TSL Auto Garage on 21/06/2022.

The following information were recorded: -

<i>Registration Number</i>	: SNA 3394Y
<i>Make & Model</i>	: Volvo S60 D2
<i>Chassis Number</i>	: YV1FS84ABE2302334
<i>Year of Registration</i>	: 2014
<i>Engine Capacity</i>	: 1560 cc
<i>Body colour</i>	: Silver

The following are our observation / comments:-

The vehicle sustained damages at the front portion. (Details see photographs enclosed)

The repaired M/s TSL Auto Garage had agreed to undertake the repair of vehicle SNA 3394Y at Lump Sum \$15,500.00.

Enclosed please find damaged vehicle's photos and out invoices for your necessary action.

Yours faithfully



Thevan Thomas Karthikesavan
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.