

ASS. REC. BY:

REF:

SMO/ CS/SMO22005902/Kqy3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. CMTD2202126/GPL

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$93k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3-7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMA 466X

Yr Regn:

10, 19

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c

1496

Colour

M. Purple

A/C:

Insured / Std / NI / NA

Sp. Reading

57123

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

AU1 1319150

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

2

mm

R/Bal.

3

mm

L/Bal.

2

mm

L/Bal.

3

mm

D.O.A.

19/6/22

D.O.I.

21/6/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Got BI

22/06/22@12.29pm revised to Gnoh PAU Loong by email.

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

: Fixing

: Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

AUTOLUTION
CARTIMES
CarTimes Autolution Pte Ltd
160 Sin Ming Drive AutoCity
#02-04 Singapore 575722
Tel : 6471 5111
Email : claims@cartimes.com.sg

Not Notion
U/Ly &
Memory After Pain
5-7days

VEHICLE NO: SMQ466X

MODEL: HONDA VEZEL

CHASSIS NO: RU1-1319150

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)	
<u>PARTS (LIST ITEMS)</u>		
TAILGATE	\$ <i>B</i> 980.00	✓
TAILGATE INNER TRIM	\$ 200.00	?
TAILGATE LOCK ASSY	\$ <i>Tu</i> 120.00	✓
REAR WINDSCREEN MOULDING	\$ <i>tu</i> 80.00	✓
TAILGATE LAMP RHS	\$ <i>CM</i> 460.00	✓
TAILGATE LAMP LHS	\$ 460.00	?
TAIL LAMP RHS	\$ 660.00	?
TAIL LAMP LHS	\$ 660.00	?
HONDA EMBLEM	\$ 40.00	?
VEZEL EMBLEM	\$ <i>tu</i> 50.00	✓
REAR BUMPER	\$ <i>B</i> 510.00	✓
REAR BUMPER RETAINER RHS	\$ <i>B</i> 30.00	X
REAR BUMPER RETAINER LHS	\$ <i>tu</i> 30.00	X
END PANEL	\$ 420.00	?
END PANEL TOP GARNISH	\$ 70.00	?
TAILGATE MOULDING	\$ 260.00	?
REAR BUMPER REFLECTOR RHS	\$ <i>B</i> 160.00	X
REAR BUMPER REFLECTOR LHS	\$ <i>tu</i> 160.00	X
REAR CORNER PANEL RHS	\$ <i>B</i> 150.00	X
REAR CORNER PANEL LHS	\$ <i>tu</i> 150.00	X
REAR WHEEL ARCH MOULDING RHS	\$ <i>B</i> 180.00	X
REAR WHEEL ARCH MOULDING LHS	\$ <i>tu</i> 180.00	X
EXHAUST	\$ <i>B</i> 540.00	X
SMART BUZZER	\$ 110.00	?
KEY ANTENNA	\$ 60.00	?
SPARE TYRE PANEL SPONGE	\$ 260.00	?
REAR FRAME STIFFENER RHS	\$ <i>B</i> 100.00	X
REAR FRAME STIFFENER LHS	\$ <i>tu</i> 100.00	X
REAR BUMPER UNDERCARRIAGE COVER	\$ 130.00	?
REAR FENDER RHS	\$ <i>B</i> 940.00	X
REAR FENDER LHS	\$ <i>B</i> 940.00	X
REAR FENDER INNER SHEILD RHS	\$ <i>B</i> 190.00	X
REAR FENDER INNER SHEILD LHS	\$ <i>tu</i> 190.00	X
SPARE TYRE PANEL	\$ 840.00	?
REAR FENDER INNER TRIM LHS	\$ 300.00	?

OCare Pte Ltd
60 Jalan Lam Li
Singapore
Tel: 622288 Fax: 626552

ARTICULAR
Claim

REAR FENDER INNER TRIM RHS		\$ 300.00	X
TAILGATE WEATHERSTRIPE		\$ 110.00	?
SPARE TYRE TOP COVER		\$ 150.00	?
WIPER MOTOR		\$ 150.00	X
SPARE TYRE TOOLS COMPARTMENT		\$ 250.00	?
	20%	\$ 11,670.00	
		\$ 2,334.00	
		\$ 9,336.00	
<u>SPECIAL NETT ITEMS</u>			
REAR SENSORS		\$ 200.00	?
CARPLATE W/HOLDER		\$ 40.00	X
WINDSCREEN SEALEANT		\$ 40.00	✓
BUMPER CLIPS 1 SET		\$ 60.00	✓
REVERSE CAMERA		\$ 200.00	X
	Total	\$ 540.00	
	TOTAL PARTS	\$ 9,876.00	

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,800.00	?
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,800.00	750
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	20
4	To provide anti-rust treatment on affected areas	\$ 100.00	?
5	Transfer tailgate parts	\$ 150.00	60
6	Remove and refit rear windscreen	\$ 150.00	120
7	Remove & refit rear sensors	\$ 100.00	50
	Labour Total :	\$ 4,200.00	
	TOTAL (PARTS & LABOUR):	\$ 14,076.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	20/06/2022 11:36 (SGT)
Date of Accident	19/06/2022 15:30 (SGT)
Exact Location of Accident	Jln Eunus, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMQ466X
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	F&B PARTY BAR
Company Reg No	5XXXX723L
Email Address	claims@cartimes.com.sg
Mobile Phone No	(Phone) +65-96249307
Alternative Phone No	+65-96249307

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Vezel
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	SI21V13563/VPL/R02
Cover Note Number	-

DRIVER

Name of Driver	ADILAH JAMES ABDULLAH
NRIC No	SXXXX086J