

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005905/KCY3Q2**Date:** 30/08/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00045142201	
Claimant Vehicle No :	SKN4231U	Insured Vehicle No :	GBC802M	
Date of Loss:	16/06/2022	Nature of Claim:	TP	Claim No: SNM22D204251/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN4231U		Engine No:	1ZRY059017
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)		Chassis No:	MR053REH104509883
Reg. Date:	12/06/2014 (Man. Year: 2014)		Odometer:	102144 km
Colour:	Metallic Black			
Engine Capacity:	1598 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55Z R16	Rear Tyre Size:	205/55Z R16
Front Left Side:	Michelin 3 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	Michelin 3 mm	Rear Right Side:	Michelin 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,080.00	1,428.00	652.00	31.35
Miscellaneous Items	223.00	178.00	45.00	20.18
Labour	684.60	625.80	58.80	8.59
Paintwork Labour	649.99	649.99	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,637.59	2,881.79	755.80	20.78
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	3,637.59	2,900.00	737.59	20.28
+ GST 7.00/7.00% (S\$)	254.63	203.00	51.63	20.28
Nett Amount (S\$)	3,892.22	3,103.00	789.22	20.28

INSPECTION

Date of Assignment:	21/06/2022	Present Location:	S & H Motor Pte Ltd (Sin Ming)
Date Inspected:	06/07/2022	Inspected At:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN4231U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Parts		2,080.00 F	*1,785.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					2,080.00	1,785.00
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	357.00
Total Parts (S\$)					2,080.00	1,428.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Misc	223.00	178.00
Sub Total (\$\$)			223.00	178.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	649.99	649.99
<u>Labour Items</u>				
2	Labour for panel/mechanical	New	684.60	625.80
Gross Labour Cost (\$\$)			1,334.59	1,275.79

Report was unsubmitted during this print-out.

< END OF ESTIMATES >