



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

SMRT TAXIS Insured's Veh No : SHB5760B

Date of Accident : 17 June 2022

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877

**GST Regn. No. : M2-8922054-2**

Mr Lee Yong Wei (Li Yonghui)

Date : 18 June 2022

Estimate To Repair SJA6505Y - Mitsubishi Lancer 1.5 Mivec GLS 4A/T

Chassis No : JMYSRCY2A8U004070

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper	\$ 869.00
02	10 ps	rear bumper clips @ \$4.50	\$ 45.00
03	1 pc	rear bumper tow cover	\$ 28.00
04	2 ps	rear bumper reflectors @ \$37.00	\$ 74.00
05	1 pc	rear bumper reinforcement	\$ 769.00
06	2 ps	rear bumper side retainer @ \$25.00	\$ 50.00
07	1 pc	bootlid	\$ 1,259.00
08	1 pc	bootlid lamp o/s	\$ 320.00
09	1 pc	bootlid weatherstrip	\$ 155.00
10	1 pc	rear end panel	\$ 520.00
11	1 pc	rear end panel top garnish	\$ 162.00
12	1 pc	bootlid lock	\$ 145.00
13	2 ps	rear number plate lamp @ \$59.00	\$ 118.00
			\$ 4,514.00
		Less 10 %	\$ 451.40
			\$ 4,062.60
		<u>SPECIAL NETT ITEMS</u>	
14	1 set	rear bumper sensor	\$ 380.00
15	1 pc	rear number plate	\$ 50.00
			\$ 430.00
		<u>LABOUR &amp; MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 60.00
02		To reinstall of rear bumper parking sensor.	\$ 80.00
03		To rust-proofing of the affected areas.	\$ 80.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00
05		Putty and spray painting of the affected portion.	\$ 850.00
06		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 150.00
			\$ 2,120.00
		Total	\$ 6,612.60