

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMR22005906/4943

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJA 6505 Y
Zanlon

at Workshop m/s

of

Insured:

SHAS 5760B

Policy No.

Claims No.

TAX / 06 / 22 / 2053

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$ 4500

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

1861

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 8 / 888

Date / Time

Action / Instruction

Sol Smith plus

code until 30-11-2022 dep 10K.

net 42611

informed will be 45 \$ 2200 (Red \$ 4763.60, 68%)

Veh No:

SJA 6505 Y

Yr Regn:

17/12/07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make:

Mit Lancer Mivec

c.c

1499

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

218294

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMYSRCY2A8U004070

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/50 R17

R:

mic

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

17/06/22

D.O.I.

22/06/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1) 28/6/22

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

TP

Lump Sum / I.B.I: (\$

2200

TOTAL

L 15/5



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

SMRT TAXIS Insured's Veh No : SHB5760B

Date of Accident : 17 June 2022

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Lee Yong Wei (Li Yonghui)

Date : 18 June 2022

not returned
due
means
22/6/22
1/5 \$2200
3 days. Tel: 68580877

Estimate To Repair SJA6505Y - Mitsubishi Lancer 1.5 Mivec GLS 4A/T

Chassis No : JMYSRCY2A8U004070

S/No	Quantity	Description	Amount
NETT ITEMS			
01	1 pc	rear bumper	\$ 869.00
02	10 ps	rear bumper clips @ \$4.50	\$ 45.00
03	1 pc	rear bumper tow cover	\$ 28.00
04	2 ps	rear bumper reflectors @ \$37.00	\$ 74.00
05	1 pc	rear bumper reinforcement	\$ 769.00
06	2 ps	rear bumper side retainer @ \$25.00	\$ 50.00
07	1 pc	bootlid	\$ 1,259.00
08	1 pc	bootlid lamp o/s	\$ 320.00
09	1 pc	bootlid weatherstrip	\$ 155.00
10	1 pc	rear end panel	\$ 520.00
11	1 pc	rear end panel top garnish	\$ 162.00
12	1 pc	bootlid lock	\$ 145.00
13	2 ps	rear number plate lamp @ \$59.00	\$ 118.00
Less 10 %			\$ 4,514.00
			\$ 451.40
			\$ 4,062.60
SPECIAL NETT ITEMS			
14	1 set	rear bumper sensor	\$ 380.00
15	1 pc	rear number plate	\$ 50.00
			\$ 430.00
LABOUR & MISC. CHARGES			
01		To check electrical lighting concerned.	\$ 60.00
02		To reinstall of rear bumper parking sensor.	\$ 80.00
03		To rust-proofing of the affected areas.	\$ 80.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00
05		Putty and spray painting of the affected portion.	\$ 850.00
06		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 150.00
Total			\$ 2,120.00
			\$ 6,612.60

Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-1764
102
1587.60
240
970
2797.60

✓
✓
✓
✓
✓
✓
X
X
X
X
X
X
X
X
200
40
20
50
X
400
500
X