



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 3046K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>LABOUR</u></b>			
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. (NPA)	NOT NECESSARY	-	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION. (NPA)	NOT NECESSARY	-	-
	ALL IN.	NOT NECESSARY	300.00	-
			300.00	-
	<b>GRAND TOTAL</b>		<b>300.00</b>	-
	<b>RECOMMENDED COST OF REPAIRS</b>			-

Report Ref No. CS/SPF22005908/Uqy3e2

NOTE: NO DAMAGE AFTER POLISH

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.