



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION (TP) Ref: CS/SPF22005908/Uqy3e2
ACCIDENT CLAIMS SECTION(SPORE POLICE FORCE)POLICE LOGISTICS BASE (PLB)1 Date: 08/07/2022
HEMMANT ROAD SINGAPORE 438675
ATTN: HAFIZUL FARHAN Code: SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 755C	Veh. Inspected	SLW 3046K
Policy No.		Coverage (\$)	0.00
Claim No.	G/20220611/2006	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	21/06/2022

2. Vehicle Particulars & Condition

Make & Model	PEUGEOT 308 (A)	c.c	1199
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	VF3LPHNYWHS166365	Colour	RED
Odometer	72492 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	PIRELLI	7 mm
L/H Front Tyre	225/45 R17	PIRELLI	7 mm
R/H Rear Tyre	225/45 R17	PIRELLI	7 mm
L/H Rear Tyre	225/45 R17	PIRELLI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/06/2022	Inspection Date	24/06/2022
Survey held at	TAN LIM MOTOR PTE LTD NO.1 DEFU LANE 6 SINGAPORE 539365		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.