



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

SPF Insured's Veh No : QX755C

Date of Accident : 11 June 2022

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Chiam Zhi Yuan, Ryan

Date : 14 June 2022

Estimate To Repair SLW3046K - PEUGEOT 308 5DR ALLURE PURETECH 1.2 A/
Chassis No : VF3LPHNYWHS166365

per U4-Mercy
24/06/2022 0900h

S/No	Quantity	Description	Amount
01		<u>LABOUR & MISC. CHARGES</u>	
02		Panel beating, knocking and straighten the necessary portion,	\$ 0.00
03		remove and renewal of parts, adjust and realign the same.	\$ 0.00
		Putty and spray painting of the affected portion.	\$ 300.00
		All in.	\$ 300.00
		<i>polish only</i>	
		<i>No Damage.</i>	
		Total	\$ 300.00

Not Authorized
U4
24/06/22
[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: