

Your Ref : CMTD2202140/RUC

Date: 01<sup>st</sup> July 2022

Our Ref : CS/SMO22005910/Kcy3e2

**M/s Sompo Insurance Singapore PL**

50 Raffles Place #03-03

Singapore Land Tower

Singapore 048623

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJT 2453P  
ACCIDENT ON 20/06/2022**

Instruction was received to inspect the vehicle Reg. No. SJT 2453P. The inspection was conducted on 22/06/2022 at the premises of M/s Cheng Hoe Motor Service, 10 Ang Mo Kio Ind Park 2A #01-04 Ang Mo Kio Autopoint, Singapore 568047.

The following vehicle information was recorded:

Registration Number	: SJP 2453P
Make/Model	: Hyundai Avante 1.6 AT ABS D/AB 2WD 4DR
Year of Registration	: 2009
Body Colour	: White
Chassis Number	: KMH DU41BMAU891785
Engine Capacity	: 1591 cc

The vehicle sustained damages at the n/s rear and front o/s portion. The undercarriage and body structure affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 17,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 5,419.00)
Nett Liability	<u>S\$ 11,581.00</u> =====

Vehicle Inspected By:



KONG SENG CHEONG  
Licensed Appraiser



K.K.LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.